

WILLIAM LEE CAR AIRCON ENGINEERING

61 UBI AVENUE 2 #08-04B

AUTOMOBILE MEGAMART SINGAPORE 408898

TEL : 6382 1006 FAX : 6383 4088

Vehicle No. SFU 5822 E

Parts and Labour Assessment

Description of part

PARTS (LIST ITEMS)

	Qty	Cost	
1 REAR TAILGATE / DD	1	1,540.30	1152 /
2 REAR TAILGATE 'HYBRID SYNERGY DRIVE' EMBLEM / REC	1	96.10	85 /
3 REAR TAILGATE 'LOGO' EMBLEM / REC	1	115.30	60 /
4 REAR TAILGATE HINGES L/R X	2	226.00	
5 REAR TAILGATE DAMPER L/R X	2	540.00	
6 REAR TAILGATE REFLECTOR L/R (RH) - GR	2 1	928.20	393 /
7 REAR TAILGATE REFLECTOR BACK RUBBER GASKET L/R X	2	159.80	
8 REAR TAILGATE WINDSCREEN MOULDING / REC	1	242.90	197 /
9 REAR TAILGATE WINDSCREEN GLASS - GR	1	1,977.60	1051 /
10 REAR TAILGATE WIPER ARM X	1	284.80	
11 REAR TAILGATE WIPER ARM BLADE X	1	98.60	
12 REAR TAILGATE WIPER ARM COVER X	1	55.60	
13 REAR TAILGATE WIPER MOTOR X	1	855.00	
14 REAR TAILGATE WINDSCREEN SEAL (TOP & LOWER) X	2	192.00	
15 REAR TAILGATE OUTER GARNISH X	1	364.80	
16 REAR TAILGATE OPENER BUTTON SENSOR X	1	285.00	
17 REAR TAILGATE NUMBER PLATE LAMP L/R X	2	188.30	
18 REAR TAILGATE INNER PULL HANDLE X	1	98.30	
19 REAR TAILGATE INNER UPHOLSTERY TRIM BOARD X	1	752.80	
20 REAR TAILGATE RUBBER GUIDE STOPPER L/R X	2	68.80	
21 REAR TAILGATE WEATHER STRIP / CRU	1	482.80	389 /
22 REAR TAILGATE MECHANISM LOCK / BT/Jammed	1	535.60	318 /
23 REAR TAILLAMP L/R (RH) - GR	2 1	1,122.20	437 /
24 REAR TAILLAMP INNER PANEL RH / DD	1	678.20	285 /
25 REAR TAILLAMP LOWER BRACKET L/R X	2	162.80	
26 REAR FENDER RH / DD	1	1,227.40	/
27 REAR FENDER GLASS MOULDING RH X	1	414.90	
28 REAR FENDER INNER TRIM BOARD L/R / CRU (RH)	2 1	1,218.00	609 /
29 REAR FENDER INNER SHIELD RH X	1	128.00	
30 REAR FENDER AIR VENT RH / CRU	1	188.00	86 /

31 REAR FENDER PROTECTOR RH	X	1	312.10	
32 REAR SLIDING DOOR RAIL COVER RH	X	1	362.20	
33 REAR SLIDING DOOR RAIL RH	X	1	382.90	
34 REAR BUMPER	/ CR4	1	1,127.20	788/
35 REAR BUMPER CENTRE PROTECTOR	- CUT	1	235.40	209/
36 REAR BUMPER END SEAL COVER L/R	(RH) - CUT	21	662.30	216/
37 REAR BUMPER REFLECTOR L/R	(RH) - GR	21	194.80	93/
38 REAR BUMPER SIDE PROTECTOR GARNISH L/R	X	2	382.50	
39 REAR BUMPER SIDE PROTECTOR COVER L/R	X	2	482.80	
40 REAR BUMPER SIDE RETAINER L/R	- GR	2	314.70	130/
41 REAR BUMPER TOW HOOK COVER	X	1	45.00	
42 REAR END PANEL TOP GARNISH	/ CR4	1	362.00	208/
43 REAR END PANEL BUZZER SENSOR	X	1	256.10	
44 REAR END PANEL KEY ANTENNA SENSOR	X	1	272.80	
45 REAR END PANEL	X R	1	782.50	
46 REAR EXHAUST SILENCER BOX	X	1	1,462.70	

7933.40
- 25%
5950.05

Percentage discount 15%

\$	22,866.10
\$	3,429.92
Sub-total	\$ 19,436.19

SPECIAL NETT ITEMS

1 REAR TAILGATE INNER UPHOLSTERY TRIM BOARD CLIPS - SET	1	80.00	X
2 REAR TAILGATE OUTER GARNISH CLIPS - SET	1	80.00	X
3 REAR TAILGATE REVERSE CAMERA	1	900.00	X
4 REAR TAILGATE WINDSCREEN SEALANT	1	160.00	40/
5 REAR TAILGATE NUMBER PLATE	1	30.00	X
6 REAR TAILGATE NUMBER PLATE HOLDER	1	60.00	X
7 REAR TAILLAMP CLIPS L/R - SET	1	80.00	X
8 REAR FENDER INNER TRIM BOARD CLIPS L/R - SET	2	200.00	20/
9 REAR FENDER INNER SHIELD CLIPS L/R - SET	2	160.00	X
10 REAR FENDER GLASS SEALANT L/R - SET	2	240.00	30/
11 REAR BUMPER CLIPS - SET	1	100.00	30/
12 REAR BUMPER END SEAL COVER CLIPS L/R - SET	2	120.00	10/
13 REAR BUMPER REVERSE SENSOR	1	650.00	X
14 REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	80.00	10/

140

Sub-total	\$ 2,940.00
------------------	--------------------

LABOUR

- | | | |
|---|----------|--------|
| 1 To provide towing charge(3 trips), scene-wkshop,wkshop-idac.idac-wkshop. | 240.00 | 80 ✓ |
| 2 To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor. | 300.00 | 30 ✓ |
| 3 To remove, reinstall top trim upholstery, cushion seat, trim garnish, trim liner carpet. | 250.00 | 80 ✓ |
| 4 To remove, reinstall Rh fender glass, tailgate windscreen. 120 + 80 | 360.00 | 200 ✓ |
| 5 To reset system after repair works. | 400.00 | X |
| 6 To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident. | 2,000.00 | 800 ✓ |
| 7 To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident. | 2,600.00 | 1800 ✓ |
| 8 To apply anti-rust chemical on repaired and replaced panel. | 180.00 | 30 ✓ |

2220

Labour Total \$ 6,330.00

Parts & Labour Total \$ 28,706.19

Best Regards,

Steve (LKK)
13/7/21

WL PL
LIS

My AC sy
10 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 5950.05

NI- 140

L- 2220

8310.05

LIS- 6648.04

= 6650 ✓