

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 58937**
Date Estimated : **12/07/2021**
Prepared By : **Foong Shiuh Jye**

- ESTIMATE REPAIR FOR -

Tay Kok Ling
2A Jalan Siantan

Singapore 268238

- ACCOUNT -

135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ9381J	WBAHS120605J970	27/07/2017	X1 sDrive18i	67362

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
Make good rear bumper & attachments parts.	850.00	0.00	850.00
To respray rear bumper	986.00	0.00	986.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	168.00	0.00	168.00
To check electrical wiring system and lighting at the rear section for proper function.	168.00	0.00	168.00
Sundries.	80.00	0.00	80.00
# To check steering geometry and conduct wheel alignment in accordance with bmw specification(no straight after accident)	531.00	0.00	531.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING RIVET	1.15	5.00	0.00	5.75
# REAR BUMPER MIDDLE TRIM PANEL (PDC)	266.95	1.00	0.00	266.95
REAR BUMPER TRIM BOTTOM (LINES)	232.45	1.00	0.00	232.45
EXPANDING RIVET BLACK	1.40	20.00	0.00	28.00
EXPANDING RIVET BLACK	1.40	3.00	0.00	4.20

SUPPLEMENTARY ITEMS

Total Labour :	2,783.00
Total Parts :	537.35
Total Labour & Parts :	3,320.35
Deduction for Excess :	
Total Repair Costs less Excess:	3,320.35
GST @7%:	232.42
Grand Total :	3,552.77

LOSS OF USE=\$100X3 DAYS
GIA SEARCH FEE=\$2.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : **b1 58937**
Date Estimated : **12/07/2021**
Prepared By : **Foong Shiuh Jye**

- ESTIMATE REPAIR FOR -
Tay Kok Ling
2A Jalan Siantan

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Singapore 268238

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ9381J	WBAHS120605J970	27/07/2017	X1 sDrive18i	67362

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

To check steering geometry and conduct wheel alignment in accordance with bmw specification(no straight after accident)

531.00 0.00 531.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

EXPANDING RIVET

1.15 5.00 0.00 5.75 ✓ REC

REAR BUMPER MIDDLE TRIM PANEL (PDC)

266.95 1.00 0.00 266.95 ✓ CUT

SUPPLEMENTARY ITEMS

Total Labour : 531.00

Total Parts : 272.70