

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

380, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Page No. : 1 of 5

Estimate No. : b1 58948
Date Estimated : 12/07/2021
Prepared By : Chua Kee Sin

- ESTIMATE REPAIR FOR -
Yeo Kwee Chew
24 Luxus Hillview

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 804501

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGZ462E	WBAYH120405P18374	30/12/2019	X2 sDrive18i	39060

DESCRIPTION

Replace rear bumper include remove attachment etc

Painting rear bumper

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

To check electrical wiring system and lighting at the rear section for proper function.

Sundries.

	VALUE
850	1,275.00
986	1,088.00
168	177.00
168	177.00
80	150.00

Total Labour 1: 2,817.00

DESCRIPTION

Abrasion gua ? Xan
Abrasion gua ? Xan
HOLDER I CAM ? Xan
REAR BUMPER RH SIDE GUIDE (M) ? Xan
REAR BUMPER TOWING EYE COVER PRIMED Xan
REAR BUMPER PANEL PRIMED (M PDC/ICA) Xan
REAR BUMPER TRIM PANEL BOTTOM PAINT ? Xan
SET MOUNTING PDC/PMA SENSOR REAR ? Xan
EXPANDING RIVET WHITE ? Xan
REAR RH REAR REFLECTOR ? Xan

QTY	PRIC	VALUE
1	2.70	2.70
1	2.70	2.70
1	23.30	23.30
1	73.95	73.95
1	51.95	51.95
1	1,191.60	1,191.60
1	514.10	514.10
1	61.00	61.00
24	3.55	85.20
1	39.05	39.05

Total Parts : 2,045.55