



方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

Joyce Mary-Ann Lim Beow Seng
Blk 32 Marine Crescent
#07-115
Singapore 440032

NOT Asheem
61 Lp @ 3000hr
Running After Pain
5 day

Dear sir
Estimate cost of repair to vehicle no. SGP 8967R
To supply

1. Tail gate	845.90	Rt	885.40	✓
2. Tail gate damper x2		Lt	240.00	X
3. Tail gate lock and motor		Not R	285.00	X 2
4. Tail gate rubber		Dis	189.00	—
5. Tail gate badge JAZZ		na	37.80	—
6. Tail gate w/s glass moulding		na	118.90	—
7. Rear panel		Rt	341.60	✓
8. Rear panel top garish		mb cont	106.80	✓
9. Rear bumper	493.70	Bu	721.00	✓
10. Rear bumper retainer x2		Alion	96.00	✓
11. Rear bumper sensor x4		Gr	450.00	2000hr
12. Tail lamp left	282	Gr	355.10	✓
13. Rear bumper clip x10		na	15.00	—
14. Rear reverse camera		Lt	200.00	X
15. Rear bumper left cover		Lt	45.00	X

Labour charges
Rust proofing
Number plate and casing
To remove and refit rear w/s glass
Panel beating
Spray painting

208
100.00 301
80.00 X
180.00 1201
880.00 800hr
900.00 600hr

Total 6,226.60

Your faithfully

Albert Poon

ALBERT POON

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: