

Section A - Accident Details

Registration Number	SHB423H
Case Reference Number	TAX/07/21/2016
Registration Date	8/9/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	YONG CHEE YOONG
Type of Accident	Head to Rear
Accident Date and Time	9/7/2021 7:35 PM
Accident Reported Date and Time	10/7/2021 9:25 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24111508
Special Instruction to ARC, if any	TP / DROVE IN
Prepared Date and Time	10/7/2021 10:32 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$600.00
Total Spray Cost	\$2,394.00	\$660.00
Total Spare Part Cost	\$13,309.74	\$1,536.50
Total Other Cost	\$2,321.88	(\$246.53)
TOTAL COST	\$19,039.62	\$2,550.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	8.0	5.0
Prepared / Adjusted By	Tuck Foo Kok	GUO QIANG (LKK) / NTUC
ARC / Surveyor Sign Off Date	14/07/2021 1:30 PM	14/07/2021 12:55 PM
Signature		
Remarks	Total number of repair days = 5 days. SUP = 0 day.	LUMP SUM REPAIR / AFTER PAINT PHOTO .

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2107-0384	Invoice Number	
Quotation Date	29.07.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$1,014.00	\$600.00
Total Labour	\$1,014.00	\$600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$80.00
TO RESPRAY REAR SPOILER	\$180.00	\$80.00
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY TROUGH BACK DOOR LH	\$180.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$2,394.00	\$660.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$475.00	\$0.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$40.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$30.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$250.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$296.88	\$296.88
Lump Sum Adjustment by Surveyor	\$0.00	(\$633.41)
Total Other Costs	\$2,321.88	(\$246.53)

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 29/07/2021

User ID : PohSuan

	75442-47030	NAME PLATE (PRIUS)	1.00	\$60.80	25.00	\$45.60	Replace	Replace	✓
		STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	✓
	67750-47071C0	TAILGATE, BOARD ASSY	0.00	\$246.90	0.00	\$0.00	Replace	Not Given	X
	76085-47910	SPOILER REAR	1.00	\$953.70	100.00	\$0.00	Replace	Repair	R
	81006-47011	3RD BRAKE LAMP	0.00	\$231.30	0.00	\$0.00	Replace	Check	X
	58307-47060	END PANEL	1.00	\$602.10	100.00	\$0.00	Replace	Repair	R
	64718-47031B0	END PANEL COVER, DECK TRIM HOLE	0.00	\$46.10	0.00	\$0.00	Replace	Check	X
	64716-47031B0	END PANEL COVER, DECK TRIM, RR	0.00	\$121.10	0.00	\$0.00	Replace	Check	X
		SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
	58311-47071	SPARE TYRE PANEL	0.00	\$667.70	0.00	\$0.00	Replace	Not Given	X
	51931-47020	CARRIER, SPARE	0.00	\$19.70	0.00	\$0.00	Replace	Not Given	X
	64778-47050	PROTECTOR, SPARE	0.00	\$143.70	0.00	\$0.00	Replace	Not Given	X
	64777-47090	CUSHION, SPARE WHEEL	0.00	\$230.80	0.00	\$0.00	Replace	Not Given	X
		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
	42611-47140	WHEEL, DISC	0.00	\$1,490.20	0.00	\$0.00	Replace	Not Given	X
	64993-47020	BOX, DECK FLOOR, RR	0.00	\$649.70	0.00	\$0.00	Replace	Not Given	X
	58416-47030B3	BOX, RR FLOOR, BOARD	0.00	\$679.60	0.00	\$0.00	Replace	Not Given	X
	64740-47031B2	PANEL ASSY, DECK LH	0.00	\$307.00	0.00	\$0.00	Replace	Not Given	X
	64730-47031B2	PANEL ASSY, DECK RH	0.00	\$307.00	0.00	\$0.00	Replace	Not Given	X
	52563-47010	TAIL LAMP BRACKET, LH	0.00	\$30.70	0.00	\$0.00	Replace	Check	X
	81561-47170	TAIL LAMP LH	1.00	\$548.40	10.00	\$493.56	Replace	Replace	✓
	61622-47030	TROUGH, BACK DOOR LH	0.00	\$110.90	0.00	\$0.00	Replace	Not Given	X
	61602-47091	FENDER RR/LH	0.00	\$766.80	0.00	\$0.00	Replace	Not Given	X
		SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	✓
		STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X
	65638-47021	FENDER LINER RR/LH	0.00	\$141.30	0.00	\$0.00	Replace	Not Given	X
	52562-47010	TAIL LAMP BRACKET, RH	0.00	\$30.70	0.00	\$0.00	Replace	Not Given	X
	81551-47180	TAIL LAMP RH	0.00	\$557.80	0.00	\$0.00	Replace	Not Given	X
Total				\$16,904.85		\$1,447.95			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		76087-47020	BUMPER LIP COVER RR/RH	1.00	\$118.10	25.00	\$88.58	Replace	Replace
Total					118.10		88.58		

✓ BR

1,536.53
+ 600.00 L/S \$2,550/-
+ 1046.88
3,183.41
-20%
2,546.73