



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21007584/Aqf3n2	
			Date: 23/08/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 2858J		Veh. Inspected	SGR 475K
Policy No.			Coverage (\$)	0.00
Claim No.	CMTD2102083/AGC		Excess (\$)	0.00
Assign From	GRACE TEO		Assign Date	13/07/2021
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH		c.c	1794
Engine No.	HIDDEN		Year of Reg.	2007
Chassis No.	ZNE100338850		Colour	GREY
Odometer	261452 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre		195/65 R15	RYDANZ	6 mm
L/H Front Tyre		195/65 R15	RYDANZ	6 mm
R/H Rear Tyre		195/65 R15	RYDANZ	6 mm
L/H Rear Tyre		195/65 R15	RYDANZ	6 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/07/2021		Inspection Date	13/07/2021
Survey held at	AUTOMOBILE HUB ENTERPRISE 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	