

nett value : 3K

SGR47SK . 2007 Jan.

TP Sompoo

Toyota Wish . 1794cc

Xiao Chen.

ZNE100338850

Front Bumper	Distorted	581.40	✓
Front Bumper Clips	new	30(SN)	✓
Front Bumper Side Holder RH.	new	35.80	✓
Front Bumper Sponge	cracked	161.40	✓
Front Bumper Reinforcement	Dented.	286.20	✓
Front Bumper Fog Lamp Cover RH.	Missing	38.90	✓
Front Grille	broken	185.20	X
Front Grille Clips	new	10(SN)	X
Headlamp RH.	cracked	878.50	✓
Bonnet	Dented	656.80	✓
Bonnet Lock	new	122.10	X
Bonnet Hinge x 02	new	85.2 x 2 = 170.40	X
Bonnet Chrome Moulding	cracked	225.15	✓
Bonnet Chrome Moulding clips	new	20(SN)	✓

SG R 47SK.

Front RH Fender	Buckled	650.10 ✓
Front RH Fender Inner Shield	torn	195.10 ✓
Front RH Fender Inner Shield clips.	new	30(SN) ✓
Engine Undercover	2 MP	287.90 +
Engine Undercover clips.	new	30(SN) +
Wiper Washer Tank.	cracked	149.50 ✓
Wiper Washer Tank Motor.	MP	132.40. +
	S.N: 80.	
	3858.80	
	2894.17	

Panel Bending	800	600
Spray Painting.	800	600
Wiring.	50.	30
		1230

total: 4204.17

n/s: 3K (Nett Value)

05 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature