

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CC6/AIG21007585/ARS3Q2  
**Date:** 05/10/2021

**REFERENCE**

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  |              |
| <b>Claimant Vehicle No :</b> | SLV947K                              | <b>Insured Vehicle No :</b> | SMY8597G     |
| Date of Loss:                | 10/07/2021                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 8080645966SG |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |             |
|-----------------------------|-----------------------------------|-------------|-------------|
| Reg No:                     | <b>SLV947K</b>                    |             |             |
| Make & Model:               | HONDA VEZEL, 1.5 (A)              | Engine No:  | L15B4429184 |
| Reg. Date:                  | 21/12/2017 (Man. Year: 2017)      | Chassis No: | RU11229180  |
| Colour:                     | Silver                            | Odometer:   | 58432 km    |
| Engine Capacity:            | 1496 cc                           |             |             |
| Market Value/New Car Price: | N/A                               |             |             |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |             |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |             |                  |             |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size:  | 215/55 R17  | Rear Tyre Size:  | 215/55 R17  |
| Front Left Side:  | Dayton 6 mm | Rear Left Side:  | Dayton 6 mm |
| Front Right Side: | Dayton 6 mm | Rear Right Side: | Dayton 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>         | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                         | 3,650.00          | 1,022.72          | 2,627.28          | 71.98         |
| Miscellaneous Items           | 0.00              | 0.00              | 0.00              |               |
| Labour                        | 2,480.00          | 430.00            | 2,050.00          | 82.66         |
| Paintwork Labour              | 0.00              | 0.00              | 0.00              |               |
| Towing                        | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>      | <b>6,130.00</b>   | <b>1,452.72</b>   | <b>4,677.28</b>   | <b>76.30</b>  |
| <b>+ GST 7.00/7.00% (S\$)</b> | <b>429.10</b>     | <b>101.69</b>     | <b>327.41</b>     | <b>76.30</b>  |

|                                                 |                 |                 |                 |              |
|-------------------------------------------------|-----------------|-----------------|-----------------|--------------|
| <b>Nett Amount (S\$)</b>                        | <b>6,559.10</b> | <b>1,554.41</b> | <b>5,004.69</b> | <b>76.30</b> |
| <b>+ Car Rental (3.0 x S\$100.00/day) (S\$)</b> |                 | 300.00          |                 |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                 | 2.00            |                 |              |
| <b>Nett Liability (S\$)</b>                     |                 | <b>1,856.41</b> |                 |              |

INSPECTION

Date of Assignment: 13/07/2021

Date Inspected: 13/07/2021

Estimated Period of Repair: 3.0 days

Inspected At:

New Hock Teck Motor Pte Ltd (HQ)  
 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit  
 Singapore 417883

**Adjuster:** ADRIAN LING**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                         | Condition     | Repairer's | Amount     |
|-----|-----|----------|-------------------------------------|---------------|------------|------------|
| 1   | 1   |          | *REAR BUMPER SIDE LH                | Deformed      | 382.60 FL  | *195.00 FL |
| 2   | 1   |          | *REAR BUMPER                        | Cut           | 820.90 FL  | *820.90 FL |
| 3   | 1   |          | *REAR BUMPER REFLECTOR LH           | Not Necessary | 84.30 FL   | *- FL      |
| 4   | 1   |          | *REAR BUMPER SIDE RETAINER LH       | Necessary     | 55.60 FL   | *35.00 FL  |
| 5   | 1   |          | *REAR TAILLAMP LH                   | Not Necessary | 542.30 FL  | *- FL      |
| 6   | 1   |          | *REAR FENDER OUTER GARNISH LH       | Cut           | 321.70 FL  | *165.00 FL |
| 7   | 1   |          | *REAR WHEEL BEARING LH              | Not Necessary | 107.50 FL  | *- FL      |
| 8   | 1   |          | *REAR FENDER LH                     | Not Necessary | 989.40 FL  | *- FL      |
| 9   | 1   |          | *REAR END PANEL                     | Not Necessary | 620.70 FL  | *- FL      |
| 10  | 1   |          | *REAR BUMPER CLIPS                  | Necessary     | 80.00 FS   | *30.00 FS  |
| 11  | 1   |          | *LH REAR SPORT RIM                  | Not Necessary | 350.00 FS  | *- FS      |
| 12  | 1   |          | *LH REAR FENDER OUTER GARNISH CLIPS | Necessary     | 60.00 FS   | *20.00 FS  |
| 13  | 1   |          | *LH REAR TAILLAMP CLIPS             | Not Necessary | 20.00 FS   | *- FS      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>4,435.00</b> | <b>1,265.90</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b> | 785.00          | 243.18          |
| <b>Total Parts (\$\$)</b>                                  | <b>3,650.00</b> | <b>1,022.72</b> |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                      | Particulars                                      | Lab.Type | Repairer's | Amount |
|-------------------------|--------------------------------------------------|----------|------------|--------|
| <u>Labour Items</u>     |                                                  |          |            |        |
| 1                       | LABOUR FOR PANEL BEATING                         | New      | 1,200.00   | 250.00 |
| 2                       | LABOUR FOR SPRAYPAINTING                         | New      | 1,000.00   | 150.00 |
| 3                       | WIRING CHECK                                     | New      | 80.00      | 30.00  |
| 4                       | TO APPLY RUST PROOF /TUFF COAT ON ACCIDENT AREAS | New      | 200.00     | 0.00   |
| Gross Labour Cost (S\$) |                                                  |          | 2,480.00   | 430.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >