



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



CITROËN

Company Reg No. 200609327M
GST Reg No. MR-8500111-X**ESTIMATE**

Invoice Name & Address		Owner Name & Vehicle Info	
Choo Chiang Chia		Cust No/Name	/Choo Chiang Chia
Blk 269 Pasir Ris Street 21		Reg No/Reg Date	SLX9330U / 18/04/2018
#03-442		Date In/Mileage	/ 0
Singapore 510269		Chassis No	VF72RHNZWJ4189133
Contact No Mobile: 88281388		Engine No	10XVA10955411
		Make/Model	CIT/C3 AIRCROSS FEEL 1.2 PURETECH 110 S&
		Colour/Trim	V6M BREATHING BLUE / 4YF AMBIANCE SERIE

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00073	Cash	13/07/2021/ 11:33		265 / AndreChow	16716	Qty	Unit Price	Disc%
Description of Goods / Services								Amount
A WHEELALIGNMENTBP								150.00 /
To Conduct Computerize Full Wheel Alignment								
E PNT88000						3	x 500	1500 2500.00
RENEW ACCIDENT DAMAGED PORTION ON FRONT BUMPER, RHF FENDER, RHF DOOR								
REPAIR RH REAR DOOR								120 200.00
E PNT88000								1520.00 /
TRANSFER RH DOOR TRIM, MECHANISM, ELECTRONICS TO FACILITATE REPAIRS								
E PNT98000						4	x 380	100.00 /
RESPRAY ACCIDENT DAMAGED PORTION ON FRONT BUMPER, RHF FENDER, RHF DOOR								
RHR DOOR AND OTHER AFFECTED PORTIONS								225.00 /
A 54900099								80.00 X
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								
A 10028901								40 80.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								70 80.00
SUPPLY ANTI CORROSION FOR AFFECTED PORTION								
M SUNDRY								70 80.00
SUPPLY BODY SEALANT FOR NEW DOOR								
M SUNDRY								80 50.00
SUNDRIES								
M SUNDRY								380.00 X
TRANSFER TYRE TO NEW RIM								
M SUNDRY								
SUPPLY RHF TYRE						1.00	884.00	0.00 884.00
M FRONT BUMPER						1.00	498.00	0.00 498.00
M BUMPR DEFLECTOR						1.00	451.00	0.00 451.00
M BUMPER MOULDING						1.00	414.00	0.00 414.00
M GUARD GRILLE						1.00	284.00	0.00 284.00
M GUARD GRILLE						1.00	124.00	0.00 124.00
M BUMPER ABSORBER						1.00	462.00	0.00 462.00
M BUMPER ABSORBER						1.00	239.00	0.00 239.00
M RANGE SUPPORT						1.00	642.00	0.00 642.00
M PILOT MODULE						1.00		

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



CITROËN

Company Reg No. 200609327M
GST Reg No. MR-6500111-X

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
Choo Chiang Chia	/Choo Chiang Chia
Blk 269 Pasir Ris Street 21	Reg No/Reg Date SLX9330U / 18/04/2018
#03-442	Date In/Mileage / 0
Singapore 510269	Chassis No VF72RHNZJ4189133
Contact No Mobile: 88281388	Engine No 10XVA10955411
	Make/Model CIT/C3 AIRCROSS FEEL 1.2 PURETECH 110 S&
	Colour/Trim V6M BREATHING BLUE / 4YF AMBIANCE SERIE

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00073	Cash	13/07/2021/ 11:33		265 / AndreChow	16716			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	BADGE	1	Xnn		1.00	259.00	0.00	259.00
M	BRACKET	1	Xnn		1.00	33.00	0.00	33.00
M	SHOCK ABSORBER	1	Xnn		1.00	145.00	0.00	145.00
M	HDLIGHT SUP SET	1	Xnn		1.00	164.00	0.00	164.00
M	BUMPER ABSORBER INFERIEUR	1	Xnn		1.00	232.00	0.00	232.00
M	FRONT WING RH	1	cut		1.00	401.00	0.00	401.00
M	WING MOULDING RH	1	cut		1.00	182.00	0.00	182.00
M	FRONT DOOR RH	1	cut		1.00	1173.00	0.00	1173.00
M	DR WEATHERSTRIP RH	1	Xnn		1.00	172.00	0.00	172.00
M	ALLOY WHEEL 6,5 J16 CH4-20	1	cut		1.00	555.00	0.00	555.00
M	FRT SWIVEL PIN RH ASS	1	Xnn		1.00	530.00	0.00	530.00
M	HUB BEARING	1	Xnn		1.00	346.00	0.00	346.00
M	WISHBONE FRONT RH ASS	1	Xnn		1.00	232.00	0.00	232.00

Estimate

SURVEYOR NAME: Steve (LKK) 13/7/21, 4:00pm

SURVEYOR SIGNATURE: OO-MAL

DATE: EXPIRIS-?

REMARKS: PIP, M BL Sy

8 7 45

Confirm & accepted by	Repairer of the following:	Parts	8,422.00
	• To resurvey before/after spray painting	Labour	4,695.00
	• To display damaged part(s) during resurvey	Standard Menu	0.00
	• Parts prices are subject to confirmation	Specialist Job	0.00
	• Third party survey is on a "Without Prejudice" basis	Diagnostics Job	0.00
Authorized signatory and company stamp		Sundry/Others	594.00
		Total (w/o GST)	13,711.00

Validity of this estimate is 14 days from date of issue. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.