



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

TPAIG. Insulin

Page No. 1

Vehicle No. SFE8287P HONDA STREAM

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
PARTS (LIST ITEMS)				
1	REAR TAILGATE <i>Dented</i>		1171.30	903
1	REAR TAILGATE LOCK <i>Dented</i>		135.00	
1	REAR TAILGATE LOCK CATCH <i>New</i>		84.00	+
2	REAR TAILGATE DAMPER LH & RH @\$300.00 <i>New</i>		600.00	+
1	REAR TAILGATE WEATHERSTRIP <i>at</i>		150.90	
1	REAR TAILGATE "STREAM" EMBLEM <i>New</i>		70.00	45.
1	REAR TAILGATE LOGO <i>New</i>		80.00	+
1	REAR TAILGATE OUTER HANDLE <i>New</i>		95.00	+
1	REAR TAILGATE INNER BOARD <i>New</i>		320.00	+
1	REAR TAILGATE UPPER GARNISH <i>New</i>		165.80	+
2	REAR TAILGATE NUMBER PLATE LAMP LH & RH @\$101.00 <i>New</i>		202.00	+
1	REAR BUMPER <i>Dented</i>		910.00	688.
2	REAR BUMPER SIDE RETAINER LH & RH @\$91.00 <i>New</i>		182.00	70.
1	REAR BUMPER TOW HOOK COVER <i>Dented</i>		95.00	35.
2	REAR TAILLAMP LH & RH @\$725.00 <i>New</i>		1450.00	+
1	REAR END PANEL INNER <i>Dented</i>		575.00	315
1	REAR END PANEL OUTER <i>Dented</i>		459.00	✓
1	REAR END PANEL TOP GARNISH <i>Dented</i>		175.00	✓
1	REAR FENDER INNER TRIM BOARD RH <i>New</i>		770.40	+
1	REAR EXHAUST SILENCER <i>New</i>		998.00	+
2	REAR EXHAUST SILENCER MOUNTING <i>New</i>		110.00	+
1	REAR WINDSCREEN SEAL <i>New</i>		92.10	✓
			8890.50	
less 20%			1778.10	20%
			7112.40	
SPECIAL NETT ITEMS				
1 SET	REVERSE SENSOR <i>Damaged</i>		280.00	200
1	REAR END PANEL SEALANT <i>New</i>		100.00	60
1 SET	REAR END PANEL TOP GARNISH CLIPS <i>New</i>		80.00	10
1 SET	REAR TAILGATE INNER TRIM CLIPS <i>New</i>		60.00	+
1	REAR WINDSCREEN SEALANT <i>New</i>		100.00	60
1	REAR WINDSCREEN INNER SHEILD <i>New</i>		120.00	+
1 SET	REAR BUMPER CLIPS <i>New</i>		80.00	30
1 SET	REAR CAR PLATE WITH HOLDER <i>New</i>		70.00	+
Total Parts			8002.40	



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

Page No. 2

Vehicle No. SFE8287P HONDA STREAM

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	OUR ASSESSMENT (\$\$)
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1600.00	1000
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1200.00	850
3	To remove and refix wiring at damaged areas	180.00	30
4	To perform anti rust treatment on affected areas	150.00	80
5	To remove / refix windscreen	150.00	120
6	To transfer bootlid mechanism	100.00	80
7	To remove and refix rear car seat	210.00	x
8	To remove and replace reverse sensor , and test	100.00	50
9	To conduct water seepage test	100.00	x
10	To remove and replace exhaust silencer	180.00	x
Labour Total :		3970.00	
TOTAL (PARTS & LABOUR):		11972.40	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 5024.40
2/S: 34K.
(Net Value)

Adrian Lj
13/07/21 K/S
00 Days.

AK