



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Ref: CS/SMR21007591/Auf3e2 Date: 27/08/2021 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 4571G	Veh. Inspected	SMY 4606R
Policy No.		Coverage (\$)	0.00
Claim No.	TAX/07/21/2018	Excess (\$)	0.00
Assign From	HUA YEN	Assign Date	13/07/2021
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA CAMRY	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	MR053BK5104024922	Colour	SILVER
Odometer	118494 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	MICHELIN	6 mm
L/H Front Tyre	215/60 R16	MICHELIN	6 mm
R/H Rear Tyre	215/60 R16	MICHELIN	6 mm
L/H Rear Tyre	215/60 R16	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	10/07/2021	Inspection Date	14/07/2021
Survey held at	JEC AUTO SERVICE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	