

SMY4606R.

TPSMRT.
Huizker.

Toyota Camry 1998cc

MR053BK5104024922

- Rear LH Door Dented 1283.40. /
- Rear LH Door Lock 2 MP 485.20. X
- Rear LH Door Weatherstripe. m 201.40. X
- Rear LH Door Inner Trim Board could 858.40. /
- Rear LH Door Inner Trim Board clips. m 30(SW). /
- Rear LH Door G(s) Regulator Gear 2nd 243.20 /
- Rear LH Door G(s) Regulator Motor m 682.10. X
- Rear Panel Outer Skirting LH 2nd 565.70. /
- Rear Panel Outer Skirting Clips. m 30(SW) /
- Rear Panel Outer Skirting Moulding LH. m 137.70. X
- Rear Panel Outer Skirting sponge. could 85.90 /
- Rear LH wheel Rim. at ~~850(SW)~~ 500(SW)
- Rear LH wheel Hub. m 758.50. X

SMY4606R.

Front LH Door	Reps	1211.70	x
Front LH Door Lock	} MP } car	462.90	x
Front LH Door weatherstripe		205.90	x
	3036.60	S-N: 560	
	2277.45		

Panel Beating.		1000	400
Spray Painting.	1340	1100	750
Wiring,		50	30
To transfer front door fittings.		150	x
To transfer rear door fittings		150	80
To dismantle rear undercarriage.		150	x
To perform wheel alignment.		150	80

total: 4177.45
 hrs: 3.3K.
 05 Days.

Total \$10842