



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
RODRIGUES JACQUELINE MARY MRS JACQUELINE MARY CHAIN 104 LENGKONG TIGA #02-371 SINGAPORE 410104  <b>Contact No</b>	<b>Cust No/Name</b>	LCV12556/RODRIGUES JACQUELINE MARY MRS J
	<b>Reg No/Reg Date</b>	SMU630S / 28/07/202
	<b>Date In/Mileage</b>	/ 0
	<b>Chassis No</b>	KNAD6811VL6457844
	<b>Engine No</b>	G3LCLP069907
	<b>Make/Model</b>	KIA/STONIC 1.0 A SX BJ3 W SUNROOF
	<b>Colour/Trim</b>	URG URBAN GREEN / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV12556	CRDVCH	13/07/2021/ 14:58	BLC	881 / Jojo Cheng	36035			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1200.00
RENEW FRT BUMPER, FRT SUPPORT PANEL, BONNET, REPAIR FRT FENDER RH & LH								
E PNT98000								1400.00
SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER RH & LH								
B WHEELALIGNMENT								120.00
To Conduct Computerize Full Wheel Alignment								
A 90000001								30.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								50.00
FRT NUMBER PLATE WITH FRAME								
M SUNDRY								40.00
APPLY SEALANT FOR ACCIDENT PORTION								
M SUNDRY								30.00
TRANSFER FRT RIGHT RIM								
M SUNDRY								20.00
Sundry								
M	COVER-FR BUMPER UPR				1.00	476.00	00.00	476.00
M	COVER-FR BUMPER,LWR				1.00	367.00	00.00	367.00
M	SKID PLATE-FR BUMPER				1.00	55.00	00.00	55.00
M	GRILLE-FRONT BUMPER				1.00	96.00	00.00	96.00
M	GRILLE ASSY-RADIATOR				1.00	324.00	00.00	324.00
M	MOULDING-FRONT BUMPER A/INTAKE				1.00	61.00	00.00	61.00
M	STRIP-FR BUMPER				1.00	27.00	00.00	27.00
M	COVER-RADIATOR GRILLE UPR				1.00	46.00	00.00	46.00
M	ABSORBER-FRONT BUMPER ENERGY				1.00	98.00	00.00	98.00
M	STIFFNER-FR BPR LWR				1.00	123.00	00.00	123.00
M	COVER-FR BUMPER FOG LAMP,RH				1.00	64.00	00.00	64.00
M	COVER-FR BUMPER FOG LAMP,LH				1.00	64.00	00.00	64.00
M	LIP ASSY-FRONT BUMPER				1.00	32.00	00.00	32.00
M	BRACKET-FR BUMPER SIDE,RH				1.00	13.00	00.00	13.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
RODRIGUES JACQUELINE MARY MRS JACQUELINE MARY CHAIN 104 LENGKONG TIGA #02-371 SINGAPORE 410104  <b>Contact No</b>	<b>Cust No/Name</b>	LCV12556/RODRIGUES JACQUELINE MARY MRS J
	<b>Reg No/Reg Date</b>	SMU630S / 28/07/202
	<b>Date In/Mileage</b>	/ 0
	<b>Chassis No</b>	KNAD6811VL6457844
	<b>Engine No</b>	G3LCLP069907
	<b>Make/Model</b>	KIA/STONIC 1.0 A SX BJ3 W SUNROOF
	<b>Colour/Trim</b>	URG URBAN GREEN / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LCV12556	CRDVCH	13/07/2021/ 14:58	BLC	881 / Jojo Cheng	36035		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	BRACKET-FR BUMPER SIDE,LH			1.00	13.00	00.00	13.00
M	LAMP ASSY-FRONT FOG,RH			1.00	234.00	00.00	234.00
M	LAMP ASSY-FRONT FOG,LH			1.00	234.00	00.00	234.00
M	AIR DUCT-FR BUMPER,RH			1.00	38.00	00.00	38.00
M	AIR DUCT-FR BUMPER,LH			1.00	38.00	00.00	38.00
M	PANEL ASSY-HOOD			1.00	904.00	00.00	904.00
M	BEAM COMPLETE-FR BUMPER			1.00	544.00	00.00	544.00
M	CARRIER ASSY-FRONT END MODULE			1.00	556.00	00.00	556.00
M	LAMP ASSY-HEAD,RH			1.00	1845.00	00.00	1845.00
M	LAMP ASSY-HEAD,LH			1.00	1845.00	00.00	1845.00
M	GUARD-AIR RADIATOR,UPR			1.00	23.00	00.00	23.00
M	GUARD-AIR,RH			1.00	14.00	00.00	14.00
M	CONDENSER ASSY-COOLER			1.00	648.00	00.00	648.00
M	RADIATOR ASSY			1.00	584.00	00.00	584.00
M	INSULATOR-RADIATOR MTG,LWR			1.00	8.00	00.00	8.00
M	BRACKET ASSY-RADIATOR MTG,UPR			1.00	21.00	00.00	21.00

Confirm &amp; accepted by

<b>Nett</b>	<b>12,405.00</b>
<b>7% GST on</b>	<b>868.35</b>
<b>Total Payable</b>	<b>13,273.35</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.