



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |  |                 |                            |  |
|--|--|-----------------|----------------------------|--|
| SMRT AUTOMOTIVE SERVICES PTE LTD<br>60 WOODLANDS INDUSTRIAL PARK<br>E4SINGAPORE 757705   |  |                 | Ref: CS/SMR21007594/Euf3n2 |  |
|  |  |                 | Date: 10/08/2021           |  |
|  |  |                 | Code: SMR                  |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |  |                 |                            |  |
| Insured Veh.   | SHC 4613U  | Veh. Inspected  | SLA 8680L                  |  |
| Policy No.   |  | Coverage (\$)   | 0.00                       |  |
| Claim No.  | TAX/07/21/2022   | Excess (\$)     | 0.00                       |  |
| Assign From  | HUA YEN  | Assign Date     | 13/07/2021                 |  |
| <b>2. Vehicle Particulars &amp; Condition</b>  |  |                 |                            |  |
| Make & Model   | LEXUS ES250  | c.c             | 2494                       |  |
| Engine No.   | HIDDEN   | Year of Reg.    | 2016                       |  |
| Chassis No.  | JTHBJ1GGX02090565  | Colour          | SILVER                     |  |
| Odometer   | 43501 KM   | Steering        | IN ORDER                   |  |
| Brakes   | IN ORDER   | Modification    | SPORTS RIM                 |  |
| General  | GOOD   |                 |                            |  |
| <b>3. Conditions of Tyres</b>  |  |                 |                            |  |
|  | Size   | Make            | Balance                    |  |
| R/H Front Tyre   | 215/55 R17   | YOKOHAMA        | 4 mm                       |  |
| L/H Front Tyre   | 215/55 R17   | YOKOHAMA        | 4 mm                       |  |
| R/H Rear Tyre  | 215/55 R17   | YOKOHAMA        | 4 mm                       |  |
| L/H Rear Tyre  | 215/55 R17   | YOKOHAMA        | 4 mm                       |  |
| <b>4. Description of Damages</b>   |  |                 |                            |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.<br>DAMAGES SEE DETAILS.  |  |                 |                            |  |
| <b>5. General Information</b>  |  |                 |                            |  |
| Accident Date  | 11/07/2021   | Inspection Date | 16/07/2021                 |  |
| Survey held at   | BORNEO MOTORS (S) PTE LTD<br>2 PANDAN CRESCENT<br>SINGAPORE 128462 |                 |                            |  |
| <b>5a. Remarks</b>   |  |                 |                            |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                 |                            |  |
| <b>5b. Estimate Days of Repair</b>   |  |                 |                            |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |  |                 | <b>3 Working Days</b>      |  |