



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21007596/Uuf3e2	
			Date: 26/07/2021	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHB 1885B	Veh. Inspected	SGZ 3468U
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/07/21/2021	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	13/07/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA VIOS (A)	c.c	1497
	Engine No.	HIDDEN	Year of Reg.	2007
	Chassis No.	MR053HY9305036600	Colour	GOLD
	Odometer	140576 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	FIRENZA	6 mm
	L/H Front Tyre	185/60 R15	FIRENZA	6 mm
	R/H Rear Tyre	185/60 R15	FIRENZA	6 mm
	L/H Rear Tyre	185/60 R15	FIRENZA	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	09/07/2021	Inspection Date	13/07/2021
	Survey held at	KS AUTOMOBILE 60 JALAN LAM HUAT, #05-68, CARROS CENTRE, SINGAPORE 737869		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	