

SME8870Y 2018 Oct.

TP Chim

Nissan Sylphy 1598cc

Veron

MNTBBAB1720033217

Front Number Plate Missing	30(SN)✓
Front Number Plate Holder and	30(SN)✓
Front Bumper Distorted	653.70✓
Front Bumper Clips. m	30(SN)✓
Front Bumper Side Holder x 02 Def	$32.1 \times 2 = 64.20$ ✓
Front Bumper Sponge. and	240.60✓
Front Bumper Reinforcement. Best	561.90✓
Front Bumper Reinforcement Stay x 02 Best	$210.9 \times 2 = 421.80$ ✓
Front Bumper Lower Grille. NH m	255.30 +
Front Bumper Sensor Damd	280(SN) 200(SN)
Front Bumper Fog Lamp x 02 RH and	316.40 $316.4 \times 2 = 632.80$
Front Bumper Fog Lamp Cover x 02 RH and	112.20 $112.2 \times 2 = 224.40$
Front Bumper Undercover Defd	238.40✓
Front Bumper Undercover Clips. m	30(SN)✓

3693.10

SME8870Y.

Front Grille *cruld* 548.30 ✓

Front Grille Logo *ML* 23.50 ✓

~~Front Grille Chrome Molding~~

Front Grille Clips. *NEC* 20(SN) ✓

Headlamp x 02. *cruld* 815x2=1630 ✓

Front Support Panel (complete) *Distal* 669.60 ✓

Front Support Panel Top Cover *del* 307.40 ✓

Front Support Panel Top Cover Clips. *NEC* 20(SN) ✓

Bonnet *2* 945.80 +

Bonnet Lock. *ML* 55.60 +

Air Can Condenser *ML* 864.40 +

Air Can Condenser Guide x 02 *cruld* 38x2=76 ✓

Radiator *NEC ML* 994.80 +

Air Resonator Box. *cruld* 258.90 ✓

Wiper Washer Tank *del* 256.20 ✓

Wiper Washer Tank Motor. *ML* 85.30 +

SMF8870Y.

LKK Auto Consultants before notifying the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Win/Win/Paid/Win" basis
- No illegal modification(s) is allowed
- Supplementary (snail) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Front Fender x 02

ALM

585.2 x 2 = 1170.40

Front Fender Inner Shield x 02

ALM

125.9 x 2 = 251.80

Front Fender Inner Shield clips

ALM

60 (SN) +

Coolant.

ALM

40 (SN) /

6379.10

S-N: 400

5741.19

Panel Beating

~~1200~~ 700

Spray Painting.

~~1200~~ 600

Wiring.

~~50~~ 30

To remove air con condenser and to top up air con gas

~~120~~ 60

To remove radiator and to top up coolant

~~120~~ 60

To remove front bumper sensor

1500

~~100~~ 50

4312.20

14,761.10

Total: 7641.19

L/S: 6.1K

05 Pass.