

ASS. REC. BY: Marcus

REF:

CC4/Fc/21007601/4ea3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

days

Res.: Yes or No

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: CB6806G

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/11/0

door m/s r/s \$1130 door glass \$15

confirmed a/s \$1250 with Any 50

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL: 6441 5655 FAX: 6441 5355/6243 8121
R.O.C No: 200104141D GST Reg. No. 20-0104141-D

TO : SXXX4801G
LIM TOR ENG
BLK 507 BEDOK NORTH AVENUE 3
07-347
SINGAPORE 460507
TEL : FAX :
PH : 96646724
ATTN :

ESTIMATE BILL

Number : EB00005726
Date : 02/07/2021
Case No : AD00011892
Vehicle No : CB6806G
Chassis: JTFST22PX00011570
Year of Mfr 2011
Policy No
Model : TOYOTA HIACE
HIROOF AUTO 14

Term:

Sn	DESCRIPTION	QTY	U PRICE	SEATER DISC	AMOUNT
1	WING MIRROR ASSEMBLY LH <i>500</i>	1.0	1,197.10	25	897.83
2	FRONT DOOR GLASS LH <i>cut</i>	1.0	589.50	25	442.13
List Price - Parts Sub Total					1,339.96
3	FRONT DOOR LH - REPAIR <i>Rx</i>	1.0			
Special Nett Price - Parts Sub Total					0.00
Parts Total					1,339.96
4	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	400.00	0	100 400.00
5	SPRAY PAINT ON THE AFFECTED AREAS	1.0	400.00	0	200 400.00
6	ANTI-RUST COATING	1.0	50.00	0	50 50.00
Labour 1 Sub Total					850.00
SINGAPORE DOLLARS : TWO THOUSAND THREE HUNDRED FORTY-THREE AND CENTS TWENTY-SIX ONLY					
Less Excess					0.00
SUBTOTAL					2,189.96
GST 7.00%					153.30
TOTAL					2,343.26

Date of accident : 01/07/2021 01:30 PM. Place : PASIR RIS DRIVE 4

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

Acknowledged by Repairer

AUTHORISED SIGNATURE

Signature:

Page 1 of 1

* N = Item not subjected to GST

Issued by : Anysia