

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AXA	DATE	: 13/07/2021
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: PC8104B		
MODEL	: TOYOTA HIACE COMMUTER		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 13-Jul-21
		TIME	: 10:25HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 2,115.30	\$ 2,115.30
2	TAILGATE LOGO <i>Neu</i>	1	\$ 55.20	\$ 55.20
3	TAILGATE 'HIACE' STICKER <i>Neu</i>	1	\$ 70.20	\$ 70.20
4	TAILGATE LOCK <i>Dented</i>	1	\$ 320.00	\$ 320.00
5	TAILGATE CATCH <i>Neu</i>	1	\$ 90.20	\$ 90.20
6	TAILGATE WEATHERSTRIP <i>Neu</i>	1	\$ 399.50	\$ 399.50
7	TAILGATE WINDSCREEN WITH MOULDING <i>Neu</i>	1	\$ 1,155.60	\$ 1,155.60
8	REAR BUMPER <i>Distorted</i>	1	\$ 530.00	\$ 530.00
9	REAR BUMPER SIDE RETAINER <i>Neu</i>	2	\$ 62.40	\$ 124.80
10	REAR BUMPER STEP PANEL <i>Dented</i>	1	\$ 430.00	\$ 430.00
11	REAR BUMPER AIR VENT LH <i>Neu</i>	1	\$ 103.50	\$ 103.50
12	REAR SPARE TYRE HOLDER BRACKET <i>Dented</i>	1	\$ 411.70	\$ 411.70
13	REAR END PANEL(OUTER) <i>Dented</i>	1	\$ 530.50	\$ 530.50

4407.70

3305.77

TOTAL PRICE \$ 6,336.50
LESS 25% \$ 1,584.13
SUB TOTAL PRICE \$ 4,752.38

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Neu</i>	1	\$ 50.00	\$ 50.00

2	TAILGATE 70KM/H <i>Nec</i>	1	\$ 20.00	\$ 20.00	<i>10</i>
3	TAILGATE WINDSCREEN SEALANT <i>Nec</i>	1	\$ 120.00	\$ 120.00	<i>60</i>
4	REAR BUMPER CLIPS(SET) <i>Nec</i>	1	\$ 20.00	\$ 20.00	
5	REAR REVERSE SENSOR <i>Dangd</i>	1	\$ 220.00	\$ 220.00	<i>200</i>
			<i>290</i> TOTAL	\$ 430.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00	<i>800</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	<i>600</i>	
3	TUFF COAT	\$ 150.00	<i>60</i>	
4	WIRING CHECK	\$ 80.00	<i>30</i>	
5	TO REMOVE AND REFIX TAILGATE MECHANISM	\$ 150.00	<i>80</i>	
6	TO REMOVE AND REFIX REAR TAILGATE WINDSCREEN	\$ 180.00	<i>120</i>	
7	TO REMOVE AND REFIX REVERSE SENSOR	\$ 120.00	<i>50</i>	
TOTAL		\$3,480.00		

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,182.38
 TOTAL LABOUR COST : \$ 3,480.00
 TOTAL REPAIR COST : \$ 8,662.38

APPROVED DETAILS

SURVEYOR :
 CONTACT NO :

FAX :

PART BY PART / LUMP SUM :
 NO OF DAYS :

Adrian Lij
n/s 1A/07/21
06 Days.

total: 5335.77
A/S: 4250.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: