

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 09/07/2021
TP Veh Reg No: GBG9083R

Estimate No: EST2100184

Date: 10 Jul 2021

Veh Reg No: **SKD2540T**

Make/Model: TOYOTA
VIOSEMANUAL

Chasis No: MR053HY9305275639

Reg. Date: 14/11/2011

Your Ref No: GBG9083R

Estimate Repair Cost to Vehicle No :SKD2540T

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC BOOT LID	784.30	
2	2 PCS BOOT LID HINGE	197.60	
3	1 PC BOOTLID LOGO	50.20	
4	1 PC BOOT LID "VIOS" EMBLEM	43.60	
5	1 PC BOOT LID "E" EMBLEM	38.60	
6	1 PC BOOT LID GARNISH	168.90	
7	2 PCS REAR NUMBER PLATE LAMP	137.20	
8	1 PC BOOT LID INNER LOCK	298.80	
9	1 PC BOOT LID RUBBER	166.40	
10	1 PC REAR FENDER RH	864.80	
11	1 PC REAR FENDER INNER TRIM	355.90	
12	1 PC REAR FENDER LH	864.80	
13	1 PC REAR FENDER INNER TRIM LH	355.90	
14	1 PC REAR WINDSCREEN RUBBER	120.00	
15	1 PC TAIL LAMP - RH	357.90	
16	1 PC TAIL LAMP PANEL RH	162.40	
17	1 PC TAIL LAMP LH	357.90	
18	1 PC TAIL LAMP PANEL LH	162.40	
19	1 PC SPARE TYRE PANEL	637.80	
20	1 PC SPARE TYRE RH SPONGE	245.20	
21	1 PC SPARE TYRE LH SPONGE	245.20	
22	1 PC SPARE TYRE	206.90	
23	1 PC REAR PANEL	680.10	
24	1 PC REAR PANEL TRIM	242.10	
25	1 PC REAR BUMPER	482.30	
26	2 PCS REAR BUMPER BRACKET	152.00	
27	2 PCS REAR BUMPER SIDE RETAINER	193.40	
28	2 PCS REAR BUMPER SMALL RETAINER	145.40	
29	1 PC REAR BUMPER REFLECTOR - RH	99.80	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 09/07/2021
TP Veh Reg No: GBG9083R

Estimate No: EST2100184

Date: 10 Jul 2021

Veh Reg No: **SKD2540T**

Make/Model: TOYOTA
VIOSEMANUAL

Chasis No: MR053HY9305275639

Reg. Date: 14/11/2011

Your Ref No: GBG9083R

Estimate Repair Cost to Vehicle No :SKD2540T

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
30	1 PC REAR BUMPER REFLECTOR - LH	99.80	
31	1 PC EXHAUST PIPE	683.40	
32	2 PCS EXHAUST PIPE MOUNTING	57.60	
		9,658.60	
	Less 25%	<u>2,414.65</u>	7,244.00
	Special Net		
33	1 PC BOOT LID NUMBER '281' STICKER	35.00	
34	1 PC REAR NUMBER PLATE	50.00	
35	1 SET REAR FENDER INNER TRIM CLIPS RH	60.00	
36	1 PC REAR FENDER STICKER	280.00	
37	1 SET REAR FENDER INNER TRIM CLIPS LH	60.00	
38	1 PC REAR FENDER STICKER LH	280.00	
39	1 PC REAR WINDSCREEN SEAL	60.00	
40	1 PC REAR WINDSCREEN SEALANT	60.00	
41	1 SET REAR PANEL TRIM CLIPS	30.00	
42	1 SET REAR BUMPER CLIPS	40.00	
43	1 SET REAR BUMPER STICKER	280.00	
		<u>1,235.00</u>	1,235.00
	Labour		
44	1 TO CHECK WIRING	50.00	
45	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	
46	1 TO REMOVE AND REFIT SEAT CUSHION	200.00	
47	1 TO REPLACE REAR FENDER STICKER	150.00	
48	1 TO REMOVE AND REFIT INNER TRIM	200.00	
49	1 TO REMOVE AND REFIX REAR EXHAUST PIPE	120.00	
50	1 TO REMOVE AND REFIT PETROL TANK	120.00	
51	1 TO SPRAY UNDERSEAL	150.00	
52	1 (REAR) TO SPRAY PAINTING	1,300.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 09/07/2021
TP Veh Reg No: GBG9083R

Estimate No: EST2100184
Date: 10 Jul 2021

Veh Reg No: SKD2540T
Make/Model: TOYOTA
VIOSEMANUAL
Chasis No: MR053HY9305275639
Reg. Date: 14/11/2011
Your Ref No: GBG9083R

Estimate Repair Cost to Vehicle No :SKD2540T

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
53	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,800.00	
		4,210.00	4,210.00
	Total		S\$ 12,689.00
	Add GST @ 7%		888.23
	Total Amount Payable		<u>S\$ 13,577.23</u>

TOTAL: SINGAPORE DOLLAR THIRTEEN THOUSAND FIVE HUNDRED SEVENTY SEVEN AND CENTS TWENTY THREE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE