

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111

FAX: 62247175

ATTN: Motor Claim Department

Estimate No: EST2100184

Date: 10 Jul 2021

Veh Reg No: SKD2540T

Make/Model: TOYOTA
VIOSEMANUAL

Chasis No: MR053HY9305275639

Reg. Date: 14/11/2011

Your Ref No: GBG9083R

Claim Type: Third Party

Accident Date: 09/07/2021

TP Veh Reg No: GBG9083R

Estimate Repair Cost to Vehicle No :SKD2540T

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC BOOT LID Distorted	784.30	✓
2	2 PCS BOOT LID HINGE Best	197.60	✓
3	1 PC BOOTLID LOGO	50.20	✓
4	1 PC BOOT LID "VIOS" EMBLEM New	43.60	✓
5	1 PC BOOT LID "E" EMBLEM	38.60	✓
6	1 PC BOOT LID GARNISH Missing	168.90	✓
7	2 PCS REAR NUMBER PLATE LAMP New	137.20	+
8	1 PC BOOT LID INNER LOCK Dented	298.80	✓
9	1 PC BOOT LID RUBBER Lot	166.40	✓
10	1 PC REAR FENDER RH Bunched	864.80	✓
11	1 PC REAR FENDER INNER TRIM New	355.90	x
12	1 PC REAR FENDER LH Repair	864.80	x
13	1 PC REAR FENDER INNER TRIM LH New	355.90	x
14	1 PC REAR WINDSCREEN RUBBER New	120.00	✓
15	1 PC TAIL LAMP - RH Cracked	357.90	✓
16	1 PC TAIL LAMP PANEL RH Dented	162.40	✓
17	1 PC TAIL LAMP LH Cracked	357.90	✓
18	1 PC TAIL LAMP PANEL LH Dented	162.40	✓
19	1 PC SPARE TYRE PANEL Repair	637.80	+
20	1 PC SPARE TYRE RH SPONGE 7 Deland	245.20	✓
21	1 PC SPARE TYRE LH SPONGE	245.20	✓
22	1 PC SPARE TYRE Repair	206.90	x
23	1 PC REAR PANEL Distorted	680.10	✓
24	1 PC REAR PANEL TRIM Deland	242.10	✓
25	1 PC REAR BUMPER Distorted	482.30	✓
26	2 PCS REAR BUMPER BRACKET Best	152.00	✓
27	2 PCS REAR BUMPER SIDE RETAINER Best NN	193.40	+
28	2 PCS REAR BUMPER SMALL RETAINER New	145.40	✓
29	1 PC REAR BUMPER REFLECTOR - RH Cracked	99.80	✓

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Estimate No: EST2100184
Date: 10 Jul 2021

Veh Reg No: SKD2540T
Make/Model: TOYOTA
VIOSEMANUAL
Chasis No: MR053HY9305275639
Reg. Date: 14/11/2011
Your Ref No: GBG9083R

Claim Type: Third Party
Accident Date: 09/07/2021
TP Veh Reg No: GBG9083R

Estimate Repair Cost to Vehicle No :SKD2540T

Quantity	Description	List Price	Amount
		SS	SS
30	1 PC REAR BUMPER REFLECTOR - LH <i>crackd</i>	99.80 ✓	
31	1 PC EXHAUST PIPE <i>Me nu</i>	683.40 ✓	
32	2 PCS EXHAUST PIPE MOUNTING <i>Nben</i>	57.60 ✓	
		9.658.60	
	Less 25%	2.414.65	7.244.00
	Special Net		
33	1 PC BOOT LID NUMBER '281' STICKER <i>neu</i>	35.00 ✓	
34	1 PC REAR NUMBER PLATE <i>Bent</i>	50.00 30	
35	1 SET REAR FENDER INNER TRIM CLIPS RH <i>neu</i>	60.00 ✓	
36	1 PC REAR FENDER STICKER <i>neu</i>	280.00 220	
37	1 SET REAR FENDER INNER TRIM CLIPS LH <i>neu</i>	60.00 ✓	
38	1 PC REAR FENDER STICKER LH <i>neu</i>	280.00 220	
39	1 PC REAR WINDSCREEN SEAL <i>neu</i>	60.00 30	
40	1 PC REAR WINDSCREEN SEALANT <i>neu</i>	60.00 30	
41	1 SET REAR PANEL TRIM CLIPS <i>neu</i>	30.00 10	
42	1 SET REAR BUMPER CLIPS <i>neu</i>	40.00 30	
43	1 SET REAR BUMPER STICKER <i>neu</i>	280.00 200	
		1.235.00	1.235.00
	Labour		
44	1 TO CHECK WIRING	50.00 30	
45	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00 ✓	
46	1 TO REMOVE AND REFIT SEAT CUSHION	200.00 80 ✓	
47	1 TO REPLACE REAR FENDER STICKER	150.00 40	
48	1 TO REMOVE AND REFIT INNER TRIM	200.00 80	
49	1 TO REMOVE AND REFIX REAR EXHAUST PIPE	120.00 ✓	
50	1 TO REMOVE AND REFIT PETROL TANK	120.00 80	
51	1 TO SPRAY UNDERSEAL	150.00 100	
52	1 (REAR) TO SPRAY PAINTING	1,300.00 1200	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111

FAX: 62247175

ATTN: Motor Claim Department

Estimate No: EST2100184

Date: 10 Jul 2021

Veh Reg No: SKD2540T

Make/Model: TOYOTA
VIOSEMANUAL

Chasis No: MR053HY9305275639

Reg. Date: 14/11/2011

Your Ref No: GBG9083R

Claim Type: Third Party

Accident Date: 09/07/2021

TP Veh Reg No: GBG9083R

Estimate Repair Cost to Vehicle No :SKD2540T

Quantity	Description	List Price	Amount
53	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	SS 1,800.00 1300	SS
	2950	4,210.00	4,210.00
Total		S\$ 12,689.00	
Add GST @ 7%		888.23	
Total Amount Payable		S\$ 13,577.23	

TOTAL: SINGAPORE DOLLAR THIRTEEN THOUSAND FIVE HUNDRED SEVENTY SEVEN AND CENTS TWENTY THREE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4-5K

Adrian L
2/s 12/07/21
10 Days

total: 8379.27

1/s: 4.5K (Nett Value)