



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21007618/Euf3n2	
			Date: 14/09/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMB 342Z	Veh. Inspected	SMM 3830D	
Policy No.		Coverage (\$)	0.00	
Claim No.	BUS/07/21/7015	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	14/07/2021	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI TL TUCSON	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	KMHJ3812VLU048816	Colour	BROWN	
Odometer	30167 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/60 R17	KUMHO	4 mm	
L/H Front Tyre	225/60 R17	KUMHO	4 mm	
R/H Rear Tyre	225/60 R17	KUMHO	4 mm	
L/H Rear Tyre	225/60 R17	KUMHO	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/07/2021	Inspection Date	02/08/2021	
Survey held at	WAH HONG MOTORS & CREDIT PTE LTD 38 TOH GUAN ROAD EAST #01-57 ENTERPRISE HUB SINGAPORE 608581			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	