



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref	: WH0765
Vehicle No.	: SMM3830D
Make & Model	: HYUNDAI TL TUCSON FL 1.6

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
1	<u>LABOUR</u> To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	400.00	200
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	400.00	200
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	30.00	✓
4	To remove, replace and focus headlamp beam	60.00	30 ✓
Labour Total :		890.00	
TOTAL (PARTS & LABOUR):		6326.60	

P-708
LR-200
N-30
L-460
1398

L/S = 1118.40
= 1100

ster (LKK) W/P
2/8/21 L/S
3 days

Resurvey After Spray

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: