



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref	:	WH0765
Vehicle No.	:	SMM3830D
Make & Model	:	HYUNDAI TL TUCSON FL 1.6

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
1	<u>LABOUR</u> To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	400.00	200
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	400.00	200
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	30.00 ✓	
4	To remove, replace and focus headlamp beam	60.00	30 ✓
Labour Total :		890.00	
TOTAL (PARTS & LABOUR):		6326.60	

ster (LKK) w/P
2/8/21 L/S
3 days
Resurvey After Spray