

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21007622/AQCN2**Date:** 23/08/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00003542103

**Claimant Vehicle No :** GBK2615G **Insured Vehicle No :** GZ6499K

Date of Loss: 11/07/2021 Nature of Claim: TP Claim No: SNM21D203843/C02/TOHHS

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **GBK2615G**

Make & Model: NISSAN NV200, 1.6 DX (A) Engine No: HR16154373D

Reg. Date: 03/03/2020 (Man. Year: 2019) Chassis No: VM20138661

Colour: Silver Odometer: 35263 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 165/80 R14 Rear Tyre Size: 165/80 R14

Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm

Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	833.10	683.79	149.31	17.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	900.00	430.00	470.00	52.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>1,733.10</b>	<b>1,113.79</b>	<b>619.31</b>	<b>35.73</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>900.00</b>		
<b>Nett Amount (\$\$)</b>	<b>1,733.10</b>	<b>900.00</b>	<b>833.10</b>	<b>48.07</b>

**INSPECTION**

Date of Assignment: 15/07/2021

Date Inspected: 14/07/2021 Inspected At: Automobile Hub Enterprise  
1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @ KAKI BUKIT  
Singapore 417883

Estimated Period of Repair: 2.0 days

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 20 Aug 2021)	
<b>Parts:</b>	N/A	NISSAN NV200 1.6 DX (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBK2615G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH FENDER	Dented	504.70 F	*504.70 FL
2	1		*FRONT RH FENDER INNER SHIELD	Torn	188.40 F	*188.40 FL
3	1		*FRONT RH FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS
4	1		*FRONT RH FENDER GLASS SEALANT	Necessary	30.00 FS	*30.00 FS
5	1		*FRONT RH WHEEL RIM COVER	Not Necessary	80.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
<b>Sub Total (\$)</b>						<b>833.10 753.10</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$)</b>						<b>0.00 69.31</b>
<b>Total Parts (\$)</b>						<b>833.10 683.79</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	400.00	200.00
2	SPRAY PAINTING	New	300.00	200.00
3	WIRING	New	50.00	30.00
4	TO PERFORM WHEEL ALIGNMENT	New	150.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>900.00</b>	<b>430.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >