

bvl

ASSIGNMENT

From _____ Date _____
 Estimated Cost: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MY
 To Inspect Vehicle No: SBS 6681X
 at Workshop m/s SBS
 of _____
 Insured: SMR 7219S
 Policy No _____
 Claims No: 2785286759SG
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

N/S	O/S

Veh No: SBS 6681X Yr Regn: 06 Aug 2013
 Type: M.Cdr / M.Cycled Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or 0530
 Make: Mercedes CC 6374
 Colour: purple/white A/C: Insured / Std / Nil / NA
 Sp Reading: 649331.1 T/Radio: Insured / Std / Nil / NA
 Eng/No: _____
 C/No: WFB62808323125123
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 275/70R22.5
 R: 11
 BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 616 mm
 L/Bal. 6 mm L/Bal. 616 mm
 D.O.A. _____ D.O.I. 14-07-21
 Survey held at w/s 1:30pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Int O/S
 The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 1 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
<u>11/7</u>	<u>No GIA provided</u> <u>Finalized & paid with Li Ming</u> 1 repair day <u>(RED \$0)</u>

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report
 11/7 TYPIST
 Date/Time, File Return to?

Days Of Repair: 1
 Resurvey No. of Trip: 1

Report Fee: TP \$450

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Insp (\$)

Survey Fee:	
Transportation:	
3 + RS \$1	
Fotos	
Other:	

AUTOTEAM ENGINEERING PTE LTD

7 Gambas Crescent #04-07 Singapore 757087
 Tel: (65) 6253 0233 Email: sales@autoteam.com.sg
 Co. Reg. No. 201205841K

bizSAFE



Quote To
SBS Transit Ltd
 Ang Mo Kio Workshop
 15 Ang Mo Kio Street 63
 Singapore 569117

- 757087 To Consultants hence notify the Repairs of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

QUOTATION

Quotation No. Q21070865
 Date 12 Jul 2021
 Terms Net 30

Attn: Mr Li Ming

S/No	Description	ManHour	ManHour Rate	Amount
------	-------------	---------	--------------	--------

- Repair Accident Bus - SBS 6681X**
- Supply 3 workers (9 Working Hours)
 - Replace Right Side Headlamp
 - Replace Right Side Headlamp Cover
 - Repair Left Side Headlamp Cover
 - Repair Front Bumper
 - Spray Painting Left & Right Side Headlamp Cover
 - Spray Painting Front Bumper

9 S\$50.00 S\$450.00

QUOTATION

Quotation No. Q21070865
 Date 12 Jul 2021
 Terms Net 30

Good Repair
 14/7/21
 1 Day



Remark(s) All Material To Be Supplied by SBST

Total S\$450.00

This is computer generated. No signature is required.