

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 9773 6360

Email: mak.auburnauto@gmail.com

Vehicle No: SJR1078G

Model: Honda Fit

QTY	Description	Repairer's Estimate
	Spare Parts - List Items	
1	Front bumper ? / BR	\$ 800.00 568✓
1	Front right fender / OD	\$ 800.00 375✓
1	Front RH headlight / CUT	\$ 800.00 570✓
1	Top RH panel (pilk) / OD	\$ 1,000.00 660✓
1	Front bonnet X nn	\$ 900.00

2173
- 20%
1738.40

\$ 4,300.00

\$ 4,300.00

c/f: \$

AMT SS

Special Nett Items

\$

S/N. Labour Charges

1	Remove and refit and panel beating	\$ 800.00	600
2	Remove, refit and replaced damage and check up rear electrical wiring	\$ 150.00	30
3	Remove and refit inner garnishes trim to assist repair	\$ 200.00	30
4	To apply undercoating on replaced panel	\$ 120.00	30
5	To Respray Painting.	\$ 900.00	600

1290

\$ 2,170.00

\$ 6,470.00

GRAND TOTAL

P- 1738-40

L- 1290

3038-40

L/S- 2422-72

= 2400

Steve (LKK)

15/7/21, 10:00

Wet AL

L/S

My AC by

5 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: