



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

TP Sampo Veron.

Page No. 1

DA17N264498

Vehicle No. 6BJ7928B
GBG5666K SUZUKI EVERY

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
	PARTS (LIST ITEMS)			
1	REAR TAILGATE <i>Revised</i>		1375.00	889
1	REAR TAILGATE LOCK <i>Br d</i>		279.00	-
1	REAR TAILGATE CENTRE LOGO <i>new</i>		65.00	-
1	REAR TAILGATE ABSORBER LH & RH @\$300.00 <i>new</i>		600.00	+
1	REAR TAILGATE INNER BOARD <i>Revised</i>		418.00	185
1	REAR TAILGATE RUBBER <i>new</i>		235.00	+
1	REAR TAILGATE OUTER HANDLE <i>new</i>		101.00	+
1	REAR BUMPER <i>Revised</i>		511.00	90
2	REAR BUMPER SIDE RETAINER LH & RH @\$80.50 <i>new</i>		161.00	+
1	REAR END PANEL <i>Distorted</i>		543.50	2
1	REAR END PANEL AIR VENT <i>Revised</i>		95.00	2
1	REAR FLOOR PANEL <i>Repair</i>		1120.00	+
1	REAR FLOOR PANEL TOP MAT <i>new</i>		695.00	+
2	REAR TAILLAMP LH & RH @\$345.60 <i>LH on Ld</i>		691.20	285
1	REAR EXHAUST SILENCER <i>Revised</i>		785.00	740
1	REAR EXHAUST SILENCER RUBBER <i>new</i>		98.00	+
1	REAR FENDER INNER SHEILD LH <i>new</i>		163.00	+
			7935.70	
		less	793.57	10%
			7142.13	
	SPECIAL NETT ITEMS			
1 SET	REAR BUMPER CLIPS <i>new</i>		100.00	30
1	REAR WINDSCREEN SEALANT <i>new</i>		100.00	60
1	REAR TAILGATE INNER BOARD CLIPS <i>new</i>		100.00	30
1	STICKER "70 KM/H" <i>new</i>		70.00	10
1	STICKER "EVERY" <i>new</i>		70.00	35
1	REAR BUMPER STICKER <i>new</i>		180.00	+
1	REAR TAILGATE STICKER <i>new</i>		250.00	+
	Total Parts		8012.13	

**ACE AUTOLUTION PTE LTD**

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
Singapore 417807
Tel: 6702 4282 Fax: 6702 4202

Page No. 2

Vehicle No. ABJ7928B
GBG5666K SUZUKI EVERY

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	OUR ASSESSMENT (\$)
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1600.00	800
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1200.00	800
3	To remove, re-fix wiring system at accident damage areas and check for proper function	150.00	30
4	To perform anti-rust treatment on affected areas	210.00	60
5	Cavity treatment on New parts	120.00	x
6	To remove and re-fix rear bootlid mechanism	150.00	80
7	To conduct water seepage test	120.00	x
8	To remove and re-fix rear windscreen	120.00	✓
9	To remove and replace exhaust silencer	250.00	80
Labour Total :		3920.00	
TOTAL (PARTS & LABOUR):		11932.13	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lj
h/s 14/07/21
06 Days

Tolent: 503.62
h/s: A 2K

4.2K