

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21007631/AQCN2**Date:** 06/01/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCNA00161012008

Claimant Vehicle No : SMG5135X**Insured Vehicle No :** SJR1642C

Date of Loss: 09/07/2021

Nature of Claim: TP

Claim No: SNM21D203834/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMG5135X**

Make & Model: HONDA VEZEL, 1.5 1.5X CVT (A)

Engine No: L15B5560113

Reg. Date: 21/12/2018 (Man. Year: 2018)

Chassis No: RU11310102

Colour: Brown

Odometer: 48115 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16

Rear Tyre Size:

215/60R16

Front Left Side: Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,220.00	1,000.00	2,220.00	68.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,292.00	820.00	2,472.00	75.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	6,512.00	1,820.00	4,692.00	72.05
+ GST 7.00/7.00% (\$\$)	455.84	127.40	328.44	72.05
Nett Amount (\$\$)	6,967.84	1,947.40	5,020.44	72.05

INSPECTION

Date of Assignment: 21/07/2021

Date Inspected: 15/07/2021

Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jan 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG5135X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR-LH	Repair	1,350.00 FS	*- FS
2	1		*REAR DOOR CHECK ROD-LH	Not Necessary	90.00 FS	*- FS
3	1		*REAR DOOR LOWER SEAL-LH	Not Necessary	45.00 FS	*- FS
4	1		*REAR DOOR PROTECTOR-LH (TAPE) LOWER	Necessary	45.00 FS	*45.00 FS
5	1		*REAR WHEEL ARCH-LH	Cut	195.00 FS	*195.00 FS
6	1		*REAR DOOR STICKER-LH (TAPE) B-PILLAR	Not Necessary	45.00 FS	*- FS
7	2		*REAR DOOR STICKER-LH (TAPE) DOOR HANDLE OUTER	Not Necessary	240.00 FS	*- FS
8	1		*SIDE STEP-LHS	Cut	360.00 FS	*360.00 FS
9	1		*WHEEL RIM	Cut	650.00 FS	*400.00 FS
10	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **3,220.00** **1,000.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	200.00	0.00
2	TO DISMANTLE AND RENEW LHS REAR DOOR AND LHS SIDE STEP.TO REPAIR LHS REAR FENDER.RE-ORGINIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,500.00	400.00
3	TO RESPRAY LHS RERA DOOR AND LHS REAR FENDER	New	1,200.00	300.00
4	TO RENEW LHS REAR RIM.TO CARRY OUT WHEEL ALIGNMENT	New	200.00	120.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	0.00
Gross Labour Cost (\$)			3,292.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >