



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0583/2021/KS
DATE : 15-Jul-21
WIP : 35373

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 14/7/2021

YOUR INSURED VEH NO : SJR 1642 C

CHINA TAIPING INSURANCE (SG) PTE LTD

105 CECIL STREET

#19-00 THE OCTAGON

SINGAPORE 069534

Attn:Motor Claims Dept

Tel: 6389 6541 - Fax: 6224 7175

OWNER'S NAME : MR DINESH KUMAR SUBRAMANIAM
ADDRESS : BLK 297B CHOA CHU KANG AVE 2
#06-80
SINGAPORE 682297
TELEPHONE : HP +65 81619570
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 5106437697-02
VEHICLE NO : SMG 5135 X
MODEL CODE : HONDA VEZEL
MODEL YEAR : 21/12/2018
ENGINE NO : L15B5560113
CHASSIS NO : RU11310102
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 9-Jul-21
PLACE OF ACCIDENT : CHOA CHU KANG AVE 2, CARPARK EXIT
NEAR 296B CARPARK EXIT (682296)



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SMG 5135 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 200.00	X
2	TO DISMANTLE AND RENEW LHS REAR DOOR AND LHS SIDE STEP. TO REPAIR LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,500.00	400
3	TO RESPRAY LHS REAR DOOR AND LHS REAR FENDER.	\$ 1,200.00	300
4	TO RENEW LHS REAR RIM. TO CARRY OUT WHEEL ALIGNMENT.	S/N \$ 200.00	120.
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	X
TOTAL LABOUR CHARGES		: \$ 3,292.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 5135 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	REAR DOOR - LH <i>Rep</i>	1	\$ 1,350.00	<i>P</i>
2	REAR DOOR CHECK ROD - LH <i>New</i>	1	\$ 90.00	<i>P</i>
3	REAR DOOR LOWER SEAL - LH <i>New</i>	1	\$ 45.00	<i>P</i>
4	REAR DOOR PROTECTOR - LH (TAPE) LOWER <i>New</i>	1	\$ 45.00	<i>—</i>
5	REAR WHEEL ARCH - LH <i>cut</i>	1	\$ 195.00	<i>✓</i>
6	REAR DOOR STICKER - LH (TAPE) B-PILLAR <i>X</i>	1	\$ 45.00	<i>Free</i>
7	REAR DOOR STICKER - LH (TAPE) DOOR HANDLE OUTER <i>X</i>	2	\$ 240.00	
8	SIDE STEP - LHS <i>cut</i>	S/N	\$ 360.00	<i>—</i>
9	WHEEL RIM <i>cut</i>	S/N	\$ 650.00	<i>400</i>
10	SUNDRIES <i>New</i>	1	\$ 200.00	<i>X</i>
TOTAL SPARE PARTS		:	\$ 3,220.00	
TOTAL LABOUR CHARGES		:	\$ 3,292.00	
GRAND TOTAL		:	\$ 6,512.00	

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adnan
SURVEYED DATE : 15/07/21
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : we authorised 103 days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT