

SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 91993103 / 97825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com TPA16.

TP Xiao Tong.

14 July 2021 GPT1015219.

QUOTATION FOR ACCIDENT REPAIR OF SLB4026Y HONDA SHUTTLE

THIRD PARTY INSURER: AIG

S/No.	Parts List	Qty	Amount (\$)
1.	Rear tailgate Distorted	1	\$1293.00 1193
2.	Rear tailgate windscreen moulding new	1	\$135.00 ✓
3.	Rear tailgate "Logo" emblem ?	1	\$76.00 ✓
4.	Rear tailgate "Shuttle" emblem New	1	\$78.00 ✓
5.	Rear tailgate "Hybrid" emblem	1	\$85.80 ✓
6.	Rear tailgate no plate lamp L/R new	2	\$104.80 x
7.	Rear tailgate no plate lamp garnish cruck	1	\$243.00 ✓
8.	Rear tailgate no plate top chrome new	1	\$480.00 x
9.	Rear tailgate reflector lamp L/R cruck	2	\$709.60 ✓
10.	Rear tailgate hinge L/R ?	2	\$133.20 x
11.	Rear tailgate damper L/R	2	\$330.00 x
12.	Rear tailgate weather strip ut	1	\$185.60 ✓
13.	Rear tailgate mechanism lock Damaged	1	\$397.90 ✓
14.	Rear tailgate lock striker new	1	\$39.00 x
15.	Rear tailgate inner trim cruck	1	\$435.80 ✓
16.	Rear tailgate inner trim handle Deformed	1	\$56.10 ✓
17.	Rear tailgate keyless smart sensor cruck	1	\$256.60 125
18.	Rear taillamp L/R ut.	2	\$1041.00 ✓
19.	Rear taillamp lower panel L/R Repair	2	\$510.00 x
20.	Rear bumper Distorted	1	\$1080.60 989.
21.	Rear bumper side reflector garnish L/R LH Dehd RH Missing	2	\$219.60 ✓
22.	Rear bumper side reflector L/R LH ut RH Missing	2	\$172.80 ✓
23.	Rear bumper side sponge L/R cruck	2	\$143.60 ✓
24.	Rear bumper side retainer L/R new	2	\$110.80 ✓
25.	Rear bumper towing cover missing	1	\$48.00 ✓
26.	Rear bumper inner buzzer Damaged	1	\$128.00 83
27.	Rear bumper inner cover finisher new	1	\$38.00 x
28.	Rear end panel Distorted	1	\$695.00 ✓
29.	Rear end panel garnish Dehd	1	\$205.80 ✓
30.	Rear spare tyre panel top board Dehd	1	\$305.80 ✓
31.	Rear spare tyre panel top tray Deformed	1	\$266.40 ✓
32.	Rear spare tyre panel top sponge cruck	1	\$215.00 ✓
33.	Rear spare tyre panel Buckled	1	\$1089.80 ✓
34.	Rear spare tyre panel stiffener new	1	\$186.60 x
35.	Rear sub chassis L/R Repair	2	\$770.00 x
36.	Rear sub chassis top panel L/R Repair	2	\$580.00 x
37.	Rear towing hook bracket new	1	\$238.00 x
38.	Rear fender inner trim board L/R Dehd	2	\$1698.40 796.
39.	Rear fender inner trim top cover L/R new	2	\$130.00 x
40.	Rear fender inner shield L/R torn	2	\$220.00 ✓
41.	Rear exhaust silencer box Repair	1	\$776.90 x
42.	Rear exhaust mounting new	3	\$204.00 x
43.	Rear exhaust heat shield cruck	1	\$168.00 ✓
44.	Hybrid battery air duct Dehd	1	\$430.80 255.
45.	Hybrid battery air blower new	1	\$268.80 x

Subtotal before discount \$16009.10
Discount 20% \$3201.82
Subtotal 1 \$12807.28

10745.40.
8596.32

SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 91993103 / 97825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

14 July 2021

QUOTATION FOR ACCIDENT REPAIR OF SLB4026Y HONDA SHUTTLE

THIRD PARTY INSURER: AIG

S/NETT	Parts List	Qty	Amount (\$)
1.	Rear tailgate windscreen sealant <i>new</i>	1	\$ 60 ✓
2.	Rear tailgate inner trim board clip <i>new</i>	1	\$ 30 ✓
3.	Rear tailgate reverse camera <i>Damaged</i>	1	\$ 400 ✓
4.	Rear no plate <i>Delco</i>	1	\$ 30 ✓
5.	Rear no plate garnish <i>Delco</i>	1	\$ 50 30-
6.	Rear bumper clip <i>new</i>	1	\$ 30 ✓
7.	Rear bumper reverse sensor <i>Damaged</i>	1	\$ 350 200
8.	Rear end panel sealant <i>new</i>	1	\$ 50 ✓
9.	Rear end panel garnish clip <i>new</i>	1	\$ 30 10
10.	Rear spare tyre panel sealant <i>new</i>	1	\$ 30 ✓
11.	Rear spare tyre insulator mat <i>new</i>	1	\$ 300 200
12.	Rear fender inner shield clip <i>new</i>	2	\$ 60 30
13.	Rear fender inner trim board clip <i>new</i>	2	\$ 60 ✓
S/Nett Total			\$ 1480

Labour

To check wiring and rectify electrical faults where necessary	\$ 60 30
To transfer tailgate mechanism and wiring assy	\$ 60 ✓
To remove, refix rear tailgate windscreen	\$ 150 120
To remove and replace and reinstall rear reverse sensor	\$ 120 50
To remove & refix reverse camera assy	\$ 100 50
To remove and reinstall rear interior trims, garnishes, seats, etc. for necessary repairs	\$ 160 140
To rustproof affected areas	\$ 100 80
To remove, replace and reinstall rear exhaust silencer box	\$ 120 80
To remove, refix hybrid battery	\$ 350 280
To straighten, repair, realign on front affected area and replace damaged parts	\$ 1500 1400
To spray painting on affected area	\$ 1500 1200
Total Labour Cost	\$ 4220

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts to the consumer
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total Cost of Repairs (Total cost of parts + Total labour cost) **\$ 18,507.28**

total: 13246.32
h/s: 10.6K.
09 Days

10.6K