

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

13-Jul-21

NAZ LKK  
14/7/2021 1730  
PIP  
2 DAY  
CHECK ITEM PHOTO  
BY PAINT PHOTO

## ESTIMATE REPAIR BILL FOR TOYOTA ALTIS REGN NO: SMQ 3770 Y

1 pc	Rear bumper	\$	487.00	✓ LKK
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00	? X SVC
1 pc	Rear bumper reinforcement	\$	395.00	? / DD
1 pc	End panel	\$	650.00	? XR
1 pc	End panel top garnish	\$	88.90	? X SVC
		\$	1,678.90	
		\$	419.74	Less 25%
		\$	1,259.16	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

### S/NETT

1 set	Rear bumper clips	\$	35.00	✓ NEL
1 set	Reverse sensor	\$	280.00	X SVC
Sundry		\$	50.00	X NN
To dismantle and replace new reverse sensor and reset to the same		\$	80.00	30
To dismantle / refit the inner garnish, inner lining, inner trim, cushion seat, etc to facilitate repair		\$	200.00	? X NN
To labour charge for dismantle and renew the accident damaged parts. To heat/weld and cut on the end panel. Including knock-out, straighten, repair, reshape and adjust of the bootlid etc		\$	900.00	180 360
To putty and spray painting on the bootlid, rear bumper, end panel		\$	750.00	180 360
To apply rustproofing on the repaired and replaced panels.		\$	150.00	40
		\$	3,704.16	

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

PARTS \$882.00  
LESS 25% \$661.50  
S/NETT \$35.00  
LABOUR \$790.00  
\$1,486.50 / 2 REPAIR DAYS