PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D NAZLKÝ 14/7/2021 1730 PPP 2 DAY) CHECK (TEMPHOTO) BY PALOT PHOTO)

13-Jul-21

ESTIMATE REPAIR BILL FOR TOYOTA ALTIS REGN NO: SMQ 3770 Y

1 pc	Rear bumper			\$	487.00	/CRK
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00			\$	58.00	?
1 pc	Rear bumper reinforcement			\$	395.00	?
1 pc	End panel			\$	650.00	?
1 pc	End panel top gar	ISLAKK Auto Consultants hence notify		\$	88.90	?
1 pc	Life parier top gar	the Repairer of the following: To resurvey before/after spray painting		\$	1,678.90	•
		To display damaged part(s) during resurvey	Less 25%	\$	419.74	
		Parts prices are subject to confirmation		\$	1,259.16	•
		Third party survey is on a "Without Prejudice" basis		•	,	
		No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company				
S/NETT	_	A disconducted by Bossins			25.22	NEC
1 set	Rear bumper clips	Acknowledged by Repairer Signature:		\$	35.00	YWI
1 set	Reverse sensor	Date:		\$		XNL
	To dismantle and replace new reverse sensor and reset to the same To dismantle / refit the inner garnish, inner lining, inner trim, cushion seat, etc to facilitate repair			\$	50.00	XNN
				\$	80.00	30
				\$	200.00	?
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld and cut on the end panel.					
	Including knock-out, straighten, repair, reshape and adjust of the bootlid etc To putty and spray painting on the bootlid, rear bumper, end panel			\$	900.00	180
				\$	750.00	180
	To apply rustproofing on the repaired and replaced panels.			\$	150.00	40
	,,,			\$	3,704.16	
				-		•

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.