

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

14-Jul-21

## ESTIMATE REPAIR BILL FOR MAZDA 6 REGN NO: SMR 7446 C

1 pc	End panel		\$	701.00	/ DD
1 pc	End panel top garnish		\$	149.00	? / CRK
1 pc	Mazda Logo		\$	68.00	/ NEC
1 pc	Emblem "Mazda 6"		\$	40.00	/ NEC
1 pc	Emblem "SKYACTIV"		\$	38.00	/ NEC
1 pc	Bootlid		\$	1,135.00	/ DD
1 pc	Bootlid weatherstrip		\$	115.00	/ DEF
2 pc	Bootlid hinge @\$220.00		\$	440.00	? X SVC
1 pc	Bootlid lock		\$	161.00	? / DEF
1 pc	Rear bumper		\$	1,099.00	/ CRK
1 pc	Rear bumper reinforcement		\$	539.00	/ BT
1 pc	Rear under cover		\$	123.00	? X SVC
2 pc	Rear tow hook n/s & o/s @\$50.00		\$	100.00	/ L MIS
2 pc	Rear bumper n/s & o/s reflector @\$42.00	\$42	\$	84.00	X L CRK
2 pc	Rear bumper n/s & o/s side bracket @\$41.00	SVC X	\$	42.00	? R ? X SVC
2 pc	N/s & o/s tail lamp @\$2003.00 \$1,600	\$3,200	\$	4,006.00	/ DEF
2 pc	N/s & o/s bootlid reflector @\$974.00		\$	1,948.00	? X SVC
4 pc	Reverse sensor (Original) @\$180.00 \$120.00	\$480	\$	720.00	/ DEF
				\$	11,508.00
				\$	7,867.00
Less 20%				\$	2,301.60
				\$	9,206.40

### S/NETT

1 set	Rear bumper clips		\$	48.00	/ NEC
1 set	End panel top garnish clips		\$	28.00	? / NEC
1 pc	Bootlid sticker "Premier"		\$	30.00	/ NEC

14-Jul-21

## ESTIMATE REPAIR BILL FOR MAZDA 6 REGN NO: SMR 7446 C

Sundry	\$ 50.00	XNN
To check lamp wiring	\$ 50.00	30
To dismantle and replace reverse sensor, check wiring	\$ 80.00	30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00	XNN
To labour charge for dismantle and renew the accident damaged parts. To cut/weld and heat on the end panel. Including knock-out, straighten, repair, reshape and adjust of the rear floorboard panel, rear n/s & o/s fender etc	\$ 1,200.00	900
To putty and spray painting on the rear bumper, end panel, floorboard panel, bootlid, rear n/s & o/s fender	\$ 1,400.00	900
To apply rustproofing on the repaired and replaced panels.	\$ 200.00	80
	<u>\$ 12,472.40</u>	

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

NAZ LKK  
15/7/2021 1745  
PIP  
5 DAYS  
CHECK ITEM PHOTOS  
BY PAINT PHOTOS

<p><u>LKK Auto Consultants</u> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"><li>• To resurvey before/after spray painting</li><li>• To display damaged part(s) during resurvey</li><li>• Parts prices are subject to confirmation</li><li>• Third party survey is on a "Without Prejudice" basis</li><li>• No illegal modification(s) is allowed</li><li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li></ul> <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p>
---

PARTS LESS 20% \$6,293.60  
SWIFT \$ 106.00  
LABOUR \$1,940.00  
\$8,339.60 / 5 REPAIR DAYS