

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

14-Jul-21

ESTIMATE REPAIR BILL FOR MAZDA 6 REGN NO: SMR 7446 C

1 pc	End panel	\$	701.00	DD
1 pc	End panel top garnish	\$	149.00	?
1 pc	Mazda Logo	\$	68.00	NEC
1 pc	Emblem "Mazda 6"	\$	40.00	NEC
1 pc	Emblem "SKYACTIV"	\$	38.00	NEC
1 pc	Bootlid	\$	1,135.00	DD
1 pc	Bootlid weatherstrip	\$	115.00	DEF
2 pc	Bootlid hinge @\$220.00	\$	440.00	?
1 pc	Bootlid lock	\$	161.00	?
1 pc	Rear bumper	\$	1,099.00	CRK
1 pc	Rear bumper reinforcement	\$	539.00	BT
1 pc	Rear under cover	\$	123.00	?
2 pc	Rear tow hook n/s & o/s @\$50.00	\$	100.00	L MIS R DEF
2 pc	Rear bumper n/s & o/s reflector @\$42.00	\$	84.00	L CRK R ?
2 pc	Rear bumper n/s & o/s side bracket @\$41.00	\$	42.00	?
2 pc	N/s & o/s tail lamp @\$2003.00	\$	4,006.00	DEF
2 pc	N/s & o/s bootlid reflector @\$974.00	\$	1,948.00	?
4 pc	Reverse sensor (Original) @\$180.00	\$	720.00	DEF
		\$	11,508.00	
Less 20%		\$	2,301.60	
		\$	9,206.40	

S/NETT

1 set	Rear bumper clips	\$	48.00	NEC
1 set	End panel top garnish clips	\$	28.00	?
1 pc	Bootlid sticker "Premier"	\$	30.00	NEC

14-Jul-21

ESTIMATE REPAIR BILL FOR MAZDA 6 REGN NO: SMR 7446 C

Sundry	\$	50.00	XNN
To check lamp wiring	\$	50.00	30
To dismantle and replace reverse sensor, check wiring	\$	80.00	30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	XNN
To labour charge for dismantle and renew the accident damaged parts. To cut/weld and heat on the end panel. Including knock-out, straighten, repair, reshape and adjust of the rear floorboard panel, rear n/s & o/s fender etc	\$	1,200.00	900
To putty and spray painting on the rear bumper, end panel, floorboard panel, bootlid, rear n/s & o/s fender	\$	1,400.00	900
To apply rustproofing on the repaired and replaced panels.	\$	200.00	80
	\$	12,472.40	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

NAZ LKK
15/7/2021 1745
PIP
5 DAY
CHECK ITEM PHOTO
BY RANT PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: