

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Notion
11 Sep @
Henry Ate Pain
Today

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 12.07.2021

Accident Date : 10.07.2021

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	貨 名 DESCRIPTION	单 价 Unit Price	銀 Amount 額 \$ cts.
Estimate Cost Of Repair To "Toyota Sienta" Reg. No. SLC4786G Claiming Against Your Insured Reg. No. SMX2469M			
1pc	Front Door LH		1,184.50 ✓
1pc	Front Door Sticker		39.70 ✓
1pc	Front Door Weatherstrip		231.30 X
1pc	Front Door Inner Stopper	5.00	32.90 ✓
12pcs	Front Door Trim Board Clips	17.50	60.00 X
2pcs	Door Center Pillar Protective Stickers (Top / Bottom)	56.20	35.00 X
2pcs	Door Center Pillar Safety Instruction Stickers		112.40 X
1pc	Door Center Pillar Outer		443.00 X
1pc	Sliding Door LH		1,145.00 ✓
1pc	Sliding Door Sticker		39.70 ✓
1pc	Sliding Door Inner Lock		1,092.80 X
1pc	Sliding Door Inner Lock Handle Frame		840.00 X
1pc	Sliding Door Lower Lock		185.00 ?
1pc	Sliding Door Weatherstrip		559.00 502.00
1pc	Sliding Door Protector	5.00	113.00 ✓
6pcs	Sliding Door Protector Clips		30.00 ✓
1pc	Sliding Door Inner Rear Reflective Sticker		35.00 ✓
1pc	Sliding Door Lower Roller		323.00 ?
1pc	Sliding Door Guide Motor		2,696.00 ?
1pc	Sliding Door Motor Regulator		185.70 ?
1pc	Sliding Door Trim Board	5.00	655.00 ?
15pcs	Sliding Door Trim Board Clips		75.00 ?
1pc	Sliding Door Sensor Weatherstrip		877.60 502.00
1pc	Sliding Door Glass Regulator		189.30 ?
1pc	Sliding Door Glass Regulator Motor		597.60 ?
1pc	Sliding Door Rail Lower Weatherstrip		225.00 502.00
1pc	Sliding Door Step Garnish		205.00 ✓
1pc	Sliding Door Sliding Motor		2,542.10 X
1pc	Sliding Door Hinge Upper		204.00 X
1pc	Sliding Door Hinge Middle		180.00 X
1pc	Sliding Door Hinge Lower		312.00 X
1pc	Rocker Panel LH		560.00 X
1pc	Rocker Panel Protective Sticker		17.50 ✓
1pc	Rear Fender LH		1,216.30 ✓
1pc	Rear Fender Protector	5.00	54.20 ✓
10pcs	Rear Fender Protector Clips		10.00 ✓
1pc	Rear Wheel Bearing		699.00 ?
1pc	Rear Shock Absorber		210.00 X
		C/F	18,212.60

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Thrd Party

Date: 12.07.2021

Accident Date : 10.07.2021

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Toyota Sienta" Reg. No. SLC4786G Claiming Against Your Insured Reg. No. SMX2469M		
		B/F	18,212.60
1pc	Rear Bumper		507.00 ✓
10pcs	Rear Bumper Clips	3.80	38.00 ✓
1pc	Rear Bumper Corner Retainer LH		60.40 ✓
1pc	Rear Bumper Protector LH		155.80 X
			18,973.80
	Less 25%		4,743.45
			14,230.35
	Front Door Visor	120.00	120.00 SN ✓
	Sliding Door Visor	120.00	120.00 SN ✓
	Sliding Door Step Garnish Top Scuff Plate R-?	280.00	280.00 SN ✓
	Rear Fender Glass Sealant	40.00	40.00 SN ✓
	Rear Fender Glass Sealer	30.00	30.00 SN ✓
	Rear Fender Glass Fastener	50.00	50.00 SN 30.00
	Rear Wheel Rim	40.00	40.00 SN ✓
	To Conduct Electrical Check	30.00	30.00 201
	To Dismantle / Refit Rear Fender Glass	100.00	100.00 601
	To Dismantle / Refit Trunk Compartment Boards & Trims	100.00	100.00 601
	To Dismantle / Refit Roof Lining	150.00	150.00 1001
	To Dismantle / Refit 2x Door Fittings / Ancillary Accessories	300.00	300.00 1201
	To Supply Rear Fender, Rocker Panel Body Sealant	100.00	100.00 X
	To Reseal Rocker Panel Lower Chip Resistant Primer	80.00	80.00 X
	To Dismantle / Replace Rear Under Carriage to Facilitate Repair	160.00	160.00 ?
	To Conduct Computerize Wheel Alignment Test	80.00	80.00 601
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel	160.00	160.00 901
		C/F	16,300.35

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 12.07.2021

Accident Date : 10.07.2021

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Toyota Sienta" Reg. No. SLC4786G Claiming Against Your Insured Reg. No. SMX2469M		
		B/F	16,300.35 1,800.00
	Labour Charge - Panel Beating, Repairing Of Floor Panel, Inner Panel, Door 'B' Pillar, Rear Fender Inner Panel etc. Cnt, Weld Rocker Panel, Rear Fender and Parts Replacement		1,650.00
	To Respray Affected Areas (2k - Pearl White) (Front Door, Rear Door, Center Pillar, Rocker Panel, Rear Fender, Rear Bumper & Petrol Cover)		
	To Reseal Paint Protection (Diamondbrite) to Spray Paint Areas.	B/I	950.00 ?
		Total :	<u>20,700.35</u>

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: