



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2200815

INV Date 14/02/2022

Reference CC4/LPC21007637/Rgs3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLR 9283D
Insured Veh. YP 6190P
Claim No. 21/21/21/VC00/024755
Policy No. Z/21/VC00/111014
Accident Date 09/07/2021
Inspection Date 22/07/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21007637/Rgs3q2 Date: 14/02/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 6190P	Veh. Inspected	SLR 9283D	
Policy No.	Z/21/VC00/111014	Coverage (\$)	0.00	
Claim No.	21/21/21/VC00/024755	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	14/07/2021	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C180 COUPE	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WDD2053402F636018	Colour	RED	
Odometer	47014 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	PIRELLI	6 mm	
L/H Front Tyre	225/50 R17	PIRELLI	6 mm	
R/H Rear Tyre	225/50 R17	PIRELLI	6 mm	
L/H Rear Tyre	225/50 R17	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/07/2021	Inspection Date	22/07/2021	
Survey held at	CYCLE & CARRIAGE INDUSTRIES PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			12 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 9283D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	RH/R TAIL LAMP (SN)	CRACKED	647.09	647.09
1	RH/R FENDER (SN)	TORN	2,964.20	2,964.10
1	ADHESIVE SEALANT (SN)	NECESSARY	776.81	776.81
1	RH/R FENDER 3/4 GLASS (SN)	NECESSARY	271.47	271.47
1	REAR WINDSHIELD (SN)	NECESSARY	1,055.83	1,055.83
3	REAR WINDSHIELD PAD (SN)	NECESSARY	16.41	16.41
1	REAR WINDSHIELD SEALING STRIP (SN)	NECESSARY	10.56	10.56
1	GLAZING REPAIR KIT (SN)	NECESSARY	480.33	480.33
1	MOUNTING RAIL PLUG (SN) (ADDITIONAL)	NECESSARY	23.03	23.03
2	MOUNTING CLIP (SN) (ADDITIONAL)	NECESSARY	23.18	23.18
1	(STR) TWO-COMPONENT ADHESIVE (SN) (ADDITIONAL)	NECESSARY	102.00	102.00
1	SEAM SEAL (SN) (ADDITIONAL)	NECESSARY	104.99	104.99
11	BLIND RIVET (SN) (ADDITIONAL)	NECESSARY	17.27	17.27
1	BLIND RIVET W CSK HEAD (SN) (ADDITIONAL)	NECESSARY	1.98	1.98
1	MODEL PLATE (SN) (ADDITIONAL)	NECESSARY	183.43	183.43
			6,678.58	6,678.48
<u>LABOUR</u>				
USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.			380.00	380.00
REMOVE & INSTALL PETROL TANK FILLING HOSE FOR NECESSARY REPAIR OR REPL.			300.00	240.00
CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE .			120.00	120.00
REMOVE & INSTALL REAR BOOT LID COMPARTMENT INTERIOR.			1,440.00	960.00
RENEW REAR WINDSHIELD .			560.00	560.00
SUPPLY 1PC REAR WINDSHIELD SOLAR FILM & 1 PC REAR RIGHT 3/4 GLASS SOLAR FILM .			400.00	400.00
REMOVE & REPLACE REAR RIGHT FENDER & REPAIR REAR BUMPER .			4,800.00	3,840.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RESPRAY REAR BUMPER ,REAR RIGHT FENDER & REAR END PANEL .		2,200.00	1,800.00
			10,200.00	8,300.00
GRAND TOTAL			16,878.58	14,978.48
RECOMMENDED COST OF REPAIRS				14,978.48

Report Ref No. CC4/LPC21007637/Rgs3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLR 9283D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLR 9283D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

