



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLR9283D

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information
WIP No 50966
Reg No/Reg Date SLR9283D / 11/12/2017
Date In/Mileage / 0
Chassis No WDD063402F636018
Engine No 27491031212445
Make/Model MB/MB C 180 COUPE (C205)
Colour/Trim 029 996 DesignoHyac/ 041 105 LeatherS.Be

SLR9283D

Account No	Terms	Date/Time Printed	CSE	Operator
WL001605	Credit	12/07/2021/ 14:44	AQ	305 / Alan Quek Ai Lun
Description of Goods / Services				
	Qty	Unit Price	Disc%	Amount

<p>M BPNSUN POLICY NO/ACC DATE : 6A419688 / 09-07-2021 DRIVE IN: 20-07-2021 / TP CAR NO: YP6190P (LONPAC INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :</p>				
A BPILAB				
USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	380.00
A BPILAB				
REMOVE & INSTALL PETROL TANK FILLING HOSE FOR NECESSARY REPAIR OR REPL				240 300.00
A BPILAB				
CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE NETT				120.00
A BPILAB				
REMOVE & INSTALL REAR BOOT LID COMPARTMENT INTERIOR				960 1440.00
A BPILAB				
RENEW REAR WINDSHIELD			0.07	560.00
S BPNSUB				
SUPPLY IPC REAR WINDSHIELD SOLAR FILM & IPC REAR RIGHT 3/4 GLASS SOLAR FILM				400.00
A BPILAB				
REMOVE & REPLACE REAR RIGHT FENDER & REPAIR REAR BUMPER				3840 4800.00
A BPIRES				
RESPRAY REAR BUMPER, REAR RIGTH FENDER & REAR END PANEL			0.03	1800 2200.00
M RH/R TAIL LAMP	1.00	647.09	00.00	647.09
M RH/R FENDER	1.00	2964.10	00.00	2964.10
M ADHESIVE SEALANT	1.00	776.81	00.00	776.81
M RH/R FENDER 3/4 GLASS	1.00	271.47	00.00	271.47
M REAR WINDSHIELD	1.00	1055.83	00.00	1055.83
M REAR WINDSHIELD PAD	3.00	5.47	00.00	16.41
M REAR WINDSHIELD SEALING STRIP	4.00	2.64	00.00	10.56
M REAR WINDSHIELD SEALING STRIP	3.00	160.11	00.00	480.33

ESTIMATE

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Nett 16,422.60
7% GST on 16422.60 1149.58
Total Payable 17,572.18

Confirmed & accepted by
Authorized signatory and company stamp

Acknowledged by Repairer

Signature: _____
Date: _____
This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg