



Mercedes-Benz

Finalization

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLR9283D

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Rasul

Vehicle & Document Information

WIP No 50966
Reg No/Reg Date SLR9283D / 11/12/2017
Date In/Mileage 22/07/2021/ 47015
Chassis No WDD2053402F636018
Engine No 27491031212445
Make/Model MB/MB C 180 COUPE (C205)
Colour/Trim 029 996 DesignoHyac/ 041 105 LeatherS.Be

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WL001605	Credit	29/09/2021/ 19:37	AQ	305 / Alan Quek Ai Lun					
M BPNSUN									
POLICY NO/ACC DATE : GA419688 // 09-07-2021									
DRIVE IN: 10-07-2021 // TP CAR NO: YP6190P (LONPAC INSURANCE)									
DATE IN/DATE SURVEY: 22-07-2021 // LKK RASUL									
BY/AUTHORIZED ON : LKK // 21-07-2021									
A BPILAB									
USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT								0.10	380.00
A BPILAB									
REMOVE & INSTALL PETROL TANK FILLING HOSE FOR NECESSARY REPAIR OR REPL									240.00
A BPILAB									
CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT									120.00
A BPILAB									
REMOVE & INSTALL REAR BOOT LID COMPARTMENT INTERIOR									960.00
A BPILAB									
RENEW REAR WINDSHIELD								0.07	560.00
S BPNSUB									
SUPPLY AND INSTALL 1 PC HURER OPTIK WINDOW FILM ON: REAR WINDSCREEN									400.00
:RH QUARTER GLASS PANEL									
A BPILAB									
REMOVE & REPLACE REAR RIGHT FENDER & REPAIR REAR BUMPER									3840.00
A BPIRES									
RESpray REAR BUMPER, REAR RIGTH FENDER & REAR END PANEL									1800.00
X RH/R TAIL LAMP									
						1.00	647.09	00.00	647.09
X RH/R FENDER									
						1.00	2964.10	00.00	2964.10
X ADHESIVE SEALANT									
						1.00	776.81	00.00	776.81
X RH/R FENDER 3/4 GLASS									
						1.00	271.47	00.00	271.47
X REAR WINDSHIELD									
						1.00	1055.83	00.00	1055.83
X REAR WINDSHIELD PAD									
						3.00	5.47	00.00	16.41
X REAR WINDSHIELD SEALING STRIP									
						4.00	2.64	00.00	10.56
X GLAZING REPAIR KIT									
						3.00	160.11	00.00	480.33

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

Finalization

ESTIMATE FOR SLR9283D

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information

WIP No 50966
Reg No/Reg Date SLR9283D / 11/12/2017
Date In/Mileage 22/07/2021/ 47015
Chassis No WDD2053402F636018
Engine No 27491031212445
Make/Model MB/MB C 180 COUPE (C205)
Colour/Trim 029 996 DesignoHyc/ 041 105 LeatherS.Be

Account No	Terms	Date/Time Printed	CSE	Operator
WL001605	Credit	29/09/2021/ 19:37	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X MOUNTING RAIL PLUG	1.00	23.03	00.00	23.03
X MOUNTING CLIP	2.00	11.59	00.00	23.18
X [STR] TWO COMPONENT ADHESIVE	1.00	102.00	00.00	102.00
X SEAM SEAL	1.00	104.99	00.00	104.99
X BLIND RIVET	11.00	1.57	00.00	17.27
X BLIND RIVET W CSK. HEAD	1.00	1.98	00.00	1.98
X MODEL PLATE	1.00	183.43	00.00	183.43

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 14,978.48
7% GST on 14978.48 1048.49
Total Payable 16,026.97

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLR9283D

SUPPLEMENTARY

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information

WIP No **50966**
Reg No/Reg Date **SLR9283D / 11/12/2017**
Date In/Mileage **22/07/2021/ 47015**
Chassis No **WDD2053402F636018**
Engine No **27491031212445**
Make/Model **MB/MB C 180 COUPE (C205)**
Colour/Trim **029 996 DesignoHyac/ 041 105 LeatherS.Be**

Account No	Terms	Date/Time Printed	CSE	Operator
WL001605	Credit	29/09/2021/ 19:37	AQ	305 / Alan Quek Ai Lun
Description of Goods / Services				
	Qty	Unit Price	Disc%	Amount

M BPNSUN

POLICY NO/ACC DATE : GA419688 // 09-07-2021
DRIVE IN: 10-07-2021 // TP CAR NO: YP6190P (LONPAC INSURANCE)
DATE IN/DATE SURVEY: 22-07-2021 // LKK RASUL
BY/AUTHORIZED ON : LKK // 21-07-2021

X MOUNTING RAIL PLUG	1.00	23.03	00.00	23.03
X MOUNTING CLIP	2.00	11.59	00.00	23.18
X [STR] TWO-COMPONENT ADHESIVE	1.00	102.00	00.00	102.00
X SEAM SEAL	1.00	104.99	00.00	104.99
X BLIND RIVET	11.00	1.57	00.00	17.27
X BLIND RIVET W CSK. HEAD	1.00	1.98	00.00	1.98
X MODEL PLATE	1.00	183.43	00.00	183.43

SUPPLEMENTARY

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cvclecarriage.com.sg

Confirmed & accepted by

	Nett	455.88
7% GST on	455.88	31.91
Total Payable		487.79

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany