

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Centre  
Singapore 408600

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Liu Chun Cheong

Date: 15 Jul 2021

## **Preliminary Advice**

Vehicle No	: SMV3594M	Accident Date	: 13/07/2021
Make	: TOYOTA HARRIER	Policy No.	: MPC21B00005800
Assignment Date	: 14/07/2021	Excess	: S\$0.00
Date of Inspection	: 15/07/2021	Est. Duration of Repair	: 4
Inspection At	: RICARDO AUTO CENTRE PTE LTD (HQ) 160 SIN MING DRIVE, #02-02, SIN MING AUTOCITY SINGAPORE 575722		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,911.50
Revised Amount	:S\$	4,588.00
Check Items (Estimated)	:S\$	1,389.00
Total	:S\$	5,977.00

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	105,000.00
COE / PARF Rebate	:S\$	51,474.00
Salvage Value	:S\$	
Margin for Repair	:S\$	53,526.00

### **Remarks**

- ( x ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :