Vecon.

TP AXA.

## **MCS** Garage

10 Kaki Bukit Road 2 #03-25, First East Centre Singapore 471868 Tel: 9270 0917 / 6538 4322

Vehicle number: <u>SMT7949H</u> Vehicle Made & Model: <u>HONDA STREAM</u>

| Qty | List Items                               | Amount \$     |
|-----|--|---------------|
| 1   | Tailgate Device                          | 1,275.60 983. |
| -   | Tailgate glass moulding her              | 121.30        |
| 1   | Tailgate emblem "H"                      | 48.80 *       |
| 1   | Tailgate emblem "STREAM"                 | 58.60         |
| 1   | Tailgate outer garnish ****              | 181.90 × ,    |
| _   | Tailgate inner lock Dane                 | 230.70        |
| 1   | Tailgate inner pull pocket               | 86.60 *       |
| 1   | Tailgate inner trim board                | 311.50 *      |
| 1   | Tailgate w/strip                         | 186.90 +      |
| 1   |  | 362.40 *      |
| 2   | Tailgate dampers @ 181.20 XLC ~          | 1,082.40      |
| 2   | Taillamps - L/R @ 541.20                 | 683.60        |
| 1   | Rear bumper Delad                        | 97.60         |
| 2   | Rear bumper side retainers - L/R @ 48.80 | 163.00        |
| 2   | Rear bumper lower brackets @ 81.50       |               |
| 1   | Rear end panel Rew                       | 560.90        |
| 1   | Rear end panel garnish 2                 | 211.30 \      |
| 1   | Rear exhaust silencer                    | 541.70 \      |
| 1   | Rear spare wheel carrier Man             | 211.50        |
| 1   | Rear spare wheel carrier lock catch      | 110.50        |
|     | Sub-to                                   |               |
|     | Less 2                                   | 1,305.36      |
|     | Total                                    | List 5,221.44 |

2337.80.

Vehicle number: SMT7949H

Vehicle Made & Model: HONDA STREAM

## Special Nett Items

1 set Tailgate glass sealant Nuc

1 set Rear reverse sensor Dand

1 set Rear bumper clip

| 295                | 80.00 €0 |
|--------------------|----------|
| 212                | 280.00 m |
|                    | 35.00    |
| Total Special Nett | 395.00   |

## Labour charges

| To check rear electrical wiring                         |               | 50.00 39      |
|---|---------------|---------------|
| To remove, refix rear interior trims to assist repair   |               | 120.00 40     |
| - C. t. Ilasta alasa                                    | 47.0          | 180.00 120    |
| To remove, refix rear reverse sensor                    | 470           | 80.00 50      |
| To respray undercoating                                 |               | 100.00 30     |
| To respray painting and etc                             |               | 1,080.00 600. |
| Panel beating, cut, weld remove & replacing above parts | 1,200.00 600. |               |
|   | l Labour      | 2,810.00      |

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

8,426.44

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 3635.24. Hs: 1.61c (Nett Value). 0 A Days.