



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21007646/Guf3n2	
			Date: 04/08/2021	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SMB 250E	Veh. Inspected	SME 9111Z
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/07/21/1019	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	14/07/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	SUBARU FORESTER 2.0	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JF1SJGK85HG085067	Colour	WHITE
	Odometer	109392 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	255/45 ZR19	PIRELLI	6 mm
	L/H Front Tyre	255/45 ZR19	PIRELLI	6 mm
	R/H Rear Tyre	255/45 ZR19	PIRELLI	6 mm
	L/H Rear Tyre	255/45 ZR19	PIRELLI	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	12/07/2021	Inspection Date	15/07/2021
	Survey held at	CARZ AUTO SERVICES PTE LTD 1 KAKI BUKIT AVE 6 #02-35 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	