

ASS. REC. BY: gufSMR

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SME 9111Z
 at Workshop m/s of Carz Auto
 Insured: SMB 250E
 Policy No. _____
 Claims No. BUS/07/21/1019
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$75K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 2 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SME9111Z Yr Regn: 28 May 2017
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Subaru Forester c.c. 1998
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 109392 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 15-07-21Survey held at w/s

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

30/7/2021 Finalize final fig L/S \$700, 2 repair days.

(RED \$1787.30; 72%)

Date/Time, File Pass to?

☐

: Preli. Report

1) 3/8 TYPIST

☐

: Final Report

Date/Time, File Return to?

2)

Report Fee: TP

Lump Sum / \$700

Days Of Repair: 2Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Insp (\$ _____)

☐

: Misc. Insp (\$ _____)

Survey Fee:

Transportation:

S + RS SI

Photos

Other:

TOTAL



CARZ AUTO SERVICES PTE LTD

UEN/ GST 201400457D

Blk 1 Kaki Bukit Avenue 6, #02-26 AutoHub@Kaki Bukit, Singapore 417883
Email: jonathan@carzauto.com.sg Tel: 65 6909 1000 Fax: 65 6909 1001

- Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

15-07-21

Insurance Company	First Capital Insurance Ltd Motor Claims Department	
Address	30 Robinson Road #10-01/02 Robinson Towers Singapore 048546	
Telephone	Fax	
Make/ Model	SUBARU FORESTER XT	
Chassis No	JF1SJGK85HG085067	Vehicle No SME9111Z
Date/Time of Accident	12 JULY 2021 / 1655HRS	

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	DESCRIPTION (LIST PARTS)	QTY	LIST PRICE \$	PARTS DISCOUNT	FINAL PRICE \$
1	REAR BUMPER <i>Wt</i>	1	\$ 720.00	10%	\$ 648.00
2	REAR BUMPER BRACKET RH <i>X</i>	1	\$ 25.00	10%	\$ 22.50
3	REINFORCEMENT BAR <i>X</i>	1	\$ 384.00	10%	\$ 345.60
4	REAR BUMPER LOWER REFLECTOR RH <i>X</i>	1	\$ 28.00	10%	\$ 25.20
5	REAR TAILLAMP RH <i>X</i>	1	\$ 520.00	10%	\$ 468.00
TOTAL LIST COST PRICE & AFTER DISCOUNT					\$ 1,509.30

SPECIAL NETT ITEM

SPECIAL ITEMS	DESCRIPTION (SPECIAL NETT PARTS)	QTY	PRICE \$	FINAL PRICE \$
1	REAR BUMPER CLIP <i>Mc</i>	4	\$ 8.00	\$ 8.00
TOTAL SPECIAL NETT ITEM				\$ 8.00

Labour Works / Panel Beating Related Works

Job Scope	Quotation
TO REMOVE AND RENEW <u>REAR</u> DAMAGED PARTS/REPLACE REALIGNED ALL AFFECTED PARTS	\$ 500.00 <i>200</i>

Spray Painting

Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 250.00 <i>200</i>

Labour Works

Job Scope	Quotation
TO REMOVE/ REFIX WIRING CHECKS	\$ 120.00
TO TUFFCOAT AFFECTED AREA	\$ 100.00
OTHER LABOUR COST	\$ 220.00

Yours Faithfully,

Annie

CARZ AUTO SERVICES PTE LTD

Person Incharge: Ms Leow Aun Nee

Job Title: Motor Claim

Mobile: 65 8363 3061

Email: aun_nee@carzauto.com.sg

GRAND TOTAL \$ 2,487.30

*2 Days
Lump sum repair / After repair photos
Guo Qiang - 82880282
15/7/2021
Guo Qiang@kkauto.com*