Performance Motors Limited

A member of the Sime Darby Group



INDIA INTERNATIONAL INSURANCE C/O LKK

Your Ref: CC4/III21007649/R1BA3 Our Ref: DS/2421555/SMJ3031J

"Without Prejudice"

Date: 01 September 2021

Subject:

ACCIDENT INVOLVING VEHICLES SMJ3031J & SMX5661D ON 30/06/21

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows: -

Cost of Repair: \$ 4,474.79 Loss of Use: \$ 300.00 (S\$100*3 days) Excess : \$ -

GIA/LTA Search: \$ 7.45 Medical fee : \$ -

Total

: \$ 4,782.24

Performance Motors Limited 1800-Call-BMW (1800-2255-269)

www.pml.com.sq

303 Alexandra Road Sime Darby Performance Centre Singapore 159941 Tel Sales 6319 0100 Tel Aftersales: 6319 0111 Fax 6474 7770

315 Alexandra Road #01-01 Sime Darby Business Centre Singapore 159944 Tel Sales 6319 0511 Tel Aftersales 6319 0527 Fax 6479 6624

280 Kampong Arang Rd East Coast Centre Singapore 438180 Tel Aftersales 6319 0888 Fax 6344 1332

Registered office 305 Alexandra Road #02-01 Vantage Automotive Centre Singapore 159942

> Co. Reg. No: 197401559W

A copy of each of the following supporting documents is enclosed:

- Copy of Final Repair Bill
- 2. GIA/LTA search slip

Loss of Rental: \$ -

3. Original Letter of Authorisation

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Evelyn Chan / Mr Suhaimi at 6319-0175 / Fax. 6479-4601 or email to pml-pbsp@simedarby.com.sg.

Yours sincerely

Cresendo Lagman

Customer Service Manager, Body & Paint

Bernard Wan

Service Manager - Body & Paint

Performance Motors Limited

A Sime Darby Motors Company

Co. Reg. No. 197401559W GST Reg. No M2-00200

303. Alexandra Road 303, Alexandra Road Sime Darby Performa Singapore 159941 Tel. 63190110 (Sale 63190111 (Afte Fax. 64747770

280, Kampong Arang East Coast Centre Singapore 438180 Tel. 63190888 (Aft Fax. 63449773

315. Alexandra Road Sime Darby Business Singapore 159944 Tel. 63190528 (63190533/530 (Fax. 64796601 64796674



SERVICE TAX INVOICE

Repair Order No. : B1 1583873 Page No. : 1 of 2

Invoice Number: 2421555 / WSB Date IN : 16/08/2021

Invoice Date : 27/08/2021

Payment Terms : 30 Days From Invoice Motor Claim Advisor: Joseph Yaguel Invoice By : Mahamod Bin Mohd Sanif

- CUSTOMER INFORMATION -

Tay Junction

733 Bukit Timah Road

#01-01 Second Avenue Junction

Singapore 269748

- INVOICE TO -85

Liberty Insurance Pte Ltd

51 Club Street

#03-00 Liberty House

Singapore 069428

ſ				
REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMJ3031J	WBATR92050LE26558	28/02/2019	X3 XDRIVE301	
(20/02/2013		46809

WBATR92050LE26558 28/02/2019 X3 XDRIV	E30I			46809
		Retail		
LABOUR 1		Price	DISCE	NETT
Replace rear bumper panel and attachments		850.00	0.00	850.00
To respray rear bumper		986.00	0.00	986.00
To check electrical wiring system and lighting at the		168.00	0.00	168.00
• •				
··		80.00	0.00	80.00
		0.00	0.00	0.00
ON 15.07.21@1000HRS. AUTHORISED BY JASPER CHUA FROM				
		0.00		
		0.00	0.00	0.00
LTA SEARCH FEE = \$7.45.		0.00	0.00	0.00
	m to			
	TOT	al Labou	ır 1:	2,084.00
		Retail		
PARTS	Qty_	Price	DISC階	NETT
REAR BUMPER PANEL PRIMED (M/PMA)	1	1,563.20	3.00	1,516.30
REAR BUMPER BOTTOM TRIM PANEL (M)	1	372.20	3.00	361.03
REAR BUMPER BOTTOM REINFORCEMENT	1	79.25	3.00	76.87
LH SIDE GUIDE FOR BUMPER	1	134.30	3.00	130.27
EXPANDING RIVET BLACK	10	1.40	3.00	13.58
	Tot	al Parts	· :	2,098.05
	Replace rear bumper panel and attachments To respray rear bumper To check electrical wiring system and lighting at the rear section for proper function. Sundries. INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT. DATE OF ACCIDENT :30.06.21. 3RD PARTY CAR :SMX5661D. YOUR REF NO:CC4/III21007649/R1 VEHICLE WAS SURVEYED BY RASUL FROM LKK CONSULTANT ON 15.07.21@1000HRS. AUTHORISED BY JASPER CHUA FROM LKK CONSULTANT VIA EMAIL ON 26.07.21. PROPOSE LOSS OF USE = \$100X3 THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION. LTA SEARCH FEE = \$7.45. PARTS REAR BUMPER BOTTOM TRIM PANEL (M) REAR BUMPER BOTTOM REINFORCEMENT LH SIDE GUIDE FOR BUMPER	Replace rear bumper panel and attachments To respray rear bumper To check electrical wiring system and lighting at the rear section for proper function. Sundries. INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT. DATE OF ACCIDENT :30.06.21. 3RD PARTY CAR :SMX5661D. YOUR REF NO:CC4/III21007649/R1 VEHICLE WAS SURVEYED BY RASUL FROM LKK CONSULTANT ON 15.07.21@1000HRS. AUTHORISED BY JASPER CHUA FROM LKK CONSULTANT VIA EMAIL ON 26.07.21. PROPOSE LOSS OF USE = \$100X3 THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION. LTA SEARCH FEE = \$7.45. Tot Tot TeAR BUMPER PANEL PRIMED (M/PMA) 1 REAR BUMPER BOTTOM TRIM PANEL (M) 1 REAR BUMPER BOTTOM REINFORCEMENT 1 LH SIDE GUIDE FOR BUMPER 1 EXPANDING RIVET BLACK 10	Retail Price Replace rear bumper panel and attachments 850.00 To respray rear bumper 986.00 To check electrical wiring system and lighting at the 168.00 rear section for proper function. Sundries. 80.00 INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT. 0.00 DATE OF ACCIDENT :30.06.21. 3RD PARTY CAR :SMX5661D. YOUR REF NO:CC4/III21007649/R1 VEHICLE WAS SURVEYED BY RASUL FROM LKK CONSULTANT ON 15.07.21@1000HRS. AUTHORISED BY JASPER CHUA FROM LKK CONSULTANT VIA EMAIL ON 26.07.21. PROPOSE LOSS OF USE = \$100X3 THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION. LTA SEARCH FEE = \$7.45. 0.00 Total Labout Total Labout Rear BUMPER PANEL PRIMED (M/PMA) 1,563.20 REAR BUMPER POTTOM TRIM PANEL (M) 1,372.20 REAR BUMPER BOTTOM TRIM PANEL (M) 1,79.25 LH SIDE GUIDE FOR BUMPER 1,134.30 EXPANDING RIVET BLACK 10.00	Retail Price DISC

вмю́ Dealer

Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-00200

303, Alexandra Road Sime Darby Performa Singapore 159941 Tel. 63190100 (Sale 63190111 (Afte Fax. 64747770 280, Kamponq Aranq Bast Coast Centre Singapore 438180 Tel. 63190888 (Aft Fax. 63449773 315. Alexandra Road Sime Darby Business Singapore 159944 Tel. 63190528 (63190533/530 (Fax. 64796601 (64796604 (



SERVICE TAX INVOICE

Repair Order No. : **B1 1583873** Page No. : **2 of 2**

Invoice Date : 27/08/2021

Motor Claim Advisor: Joseph Yaguel Payment Terms : 30 Days From Invoice

Invoice By : Mahamod Bin Mohd Sanif

Labour Charges	:	2,004.00	Total Labour & Parts Charges	: S\$	4,182.05
Parts Charges	:	2,098.05	Less Insurance Excess	: S\$	0.00
Lubricant/Misc	:	80.00	Invoice Total Amount Exclude GST	: S\$	4,182.05
			GST @ 7%	: S\$	292.74
			Invoice Total Amount Include GST	: S\$	4,474.79

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



> Back to OneMotoring



Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time:

01 Jul 2021 / 10:10:29

Receipt Date/Time: 01 Jul 2021 / 10:10:29

Tax Invoice/Receipt

Receipt No.: ITNET-00000-210701-000928

Previous Receipt No.:

S/N Item Description/ Business Transaction Reference No.		Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SMX5661D As at 30 Jun 2021/17:00:00 Insurance Co: INDIA INT'L INS PTE LTD Insurance Enquiry - SMX5661D				
Enquiry Fee 20210701100940742583		7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	542125XXXXXX4416	eNETS Credit Card		7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Performance Motors Limited A member of the Sime Darby Group

303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941



FORM B1 VERSION 1 - SEPT 2017

LETTER OF AUTHORISATION

ACCIDENT INVOLVING	SMJ3031J	_ &	SMX 566 10	ON	30-06-21
ן, איז	owner o ance Motors Lir epair and/or uninsi	of Ve nite ured	hicle Registrati d to submit, co losses arising f	on No orrespond rom the a	smu30310 d, negotiate and above accident.
I further authorise Perforr documents whatsoever in due to me in respect of my	relation to this ma	imit e atter	ed to execute, and to accept	sign, sea and rece	al and deliver all ive any payment
I hereby declare that all act on my behalf shall be good the same had been done or	valid and effectua	al to	all intents and p	nis Letter ourposes	of Authorisation whatsoever as if
I further confirm that the ac amount in respect of such of such loss and damage.	cceptance by Perf claim shall constitu	form ute tl	ance Motors L ne full discharge	.imited of my cl	of the settlement laim in respect of
Signed by:					
A				•	
Name: TAY JUNIO 1 NRIC No.: 733 Build Tirad #G4-04 Singular Tel: 6468 22-3 Fax	3 969740				
In the presence of:					
	2				
Name : NRIC No.: Joseph Yao	(Date)			
NRIC No.: Joseph Yag Performance Moto	juel rs Limited				