

ASS. REC. BY:

Tanjah 1 CC4/111 21067651/Tigaz

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: A78K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WPDate: _____ Person Contacted: Sam Vehicle: IN / OUTVeh No: SDY8382RYr Regn: 2017, SepType: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Toyota Wishc.c. 1798Colour: MaroonA/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: 82847T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: STDG 620W105 007737Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orMod: ☐ Nil / ☐ S/Rim / ☐ STD A/Rim orTyre Size: F: 195/65R16R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 23/7/2017pmSurvey held at Borneo UbiDes. of Damages: ☒ Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Rep. Format: _____

Lump Sum / L.B.K. ()

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
India International Insurance P L	S1000006 / ICIII1	Mr Soh Poh Hock (Su Baofu)
4 Cecil Street	Document No.	411A Fernvale Road
06-02 IOB Building	0	#22-76
Singapore 049711	Document Date	Singapore 791411
Attn: Motor Claims Dept	14/07/2021	Mobile: 91893288

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZGE20R	HPXNP S6	06/09/2017	SDY8382R	0	21086	67/DS/SDY8382R

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDGG20W10J007737	2ZR0A02835	60	Sam San Joi	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-GY861S ACC DATE:13/07/2021 DRIVE IN:14/07/2021 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				✓ 30.00
2	S	BP-SUBLET FRT & REAR NUMBER PLATE				bt 136.00
3	B	BP-LAB2 CHECK LIGHTING & WIRING SYSTEM				122.40
4	B	BP-LAB2 REMOVE & INSTALL AIRCON CONDENSER ASSY A ND CHARGE UP GAS				360.00
5	Z	BP-SLANT SUPPLY SEALANT (NETT)- BONNET, FRT SUPPO RT PANEL				60. 120.00
6	B	BP-LAB2 REPLACE FRT ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN FRT ACCIDENT AFFECTED AREAS				1440 4500.00
7	B	BP-RES2 RESPRAY JOB ON FRT ACCIDENT AFFECTED AREAS				1475 2950.00
8	S	BP-SUBLET TO RESET ECU AND REPROGRAMME				✓ 180.00
9	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR				✓ 180.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Amount Due	97495449. 11 days p/p Rising before paint. Less taufik @ lkkauto.com - wp 23/7/21 22pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details	
India International Insurance P L 34 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		S1000006 / ICIII1	Mr Soh Poh Hock (Su Baofu) 411A Fernvale Road #22-76 Singapore 791411 Mobile: 91893288	
		Document No.		
		0		
		Document Date		
		14/07/2021		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZGE20R	HPXNP S6	06/09/2017	SDY8382R	0	21086	67/DS/SDY8382R

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDGG20W10J007737	2ZR0A02835	60	Sam San Joi	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	B	BP-LAB2 REMOVE & INSTALL REAR COMPARTMENT CARPET, GARNISH AND TRIMMING TO ASSIST REPAIR				✓ 360.00
11	B	BP-LAB2 REPLACE & INSTALL REAR WINDSCREEN GLASS				462 495.00
12	S	BP-SUBLET INSTALL REAR WINDSCREEN GLASS 3M SOLAR F ILM				✓ 350.00
13	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW TAILGATE				✓ 360.00
14	B	BP-LAB2 REMOVE & INSTALL REAR REVERSE CAMERA				✓ 180.00
15	Z	BP-SLANT SUPPLY SEALANT (NETT)-TAILGATE, REAR END PANEL				60 120.00
16	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED REAS				3- 2160 3600.00
17	B	BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED REAS				3- 1770 2950.00
18	1	T52119-68909 FRONT BUMPER COVER,	1.00	596.90		de 596.90
19	2	T52116-68031 L/FRT BUMPER SUPPORT,	1.00	63.40		? 63.40
20	3	T52115-68031 R/FRT BUMPER SUPPORT,	1.00	63.40		? 63.40
21	4	T52611-68030 FRT BUMPER ABSORBER,	1.00	103.20		? 103.20
22	5	T52021-68020 FRT BPR REINFORCEMENT,	1.00	308.20		? 308.20
23	6	T53101-68010 GRILLE,RADIATOR	1.00	419.30		Cur 419.30

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Sublet	Less
		Lubrication/Fluid	
		Others	Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

17 UBI ROAD 4

SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
India International Insurance P L	S1000006 / ICIII1	Mr Soh Poh Hock (Su Baofu)
4 Cecil Street	Document No.	411A Fernvale Road
06-02 IOB Building	0	#22-76
Singapore 049711	Document Date	Singapore 791411
Attn: Motor Claims Dept	14/07/2021	Mobile: 91893288

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZGE20R	HPXNP S6	06/09/2017	SDY8382R	0	21086	67/DS/SDY8382R

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDGG20W10J007737	2ZR0A02835	60	Sam San Joi	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
24	7	S52161-0K040 CLIPS	10.00	4.10		41.00
25	8	T53301-68020 FRONT BONNET ASSY,	1.00	988.40		988.40
26	9	T53341-68020 FRT BONNET INSULATOR,	1.00	415.60		415.60
27	0	T90467-09050 CLIP(HOOD INSULATOR)	6.00	2.90		17.40
28	1	T53420-68030 L/FRT BONNET HINGE,	1.00	59.60		59.60
29	2	T53410-68030 R/FRT BONNET HINGE,	1.00	59.60		59.60
30	3	T53510-68050 FRONT BONNET LOCK,	1.00	94.40		94.40
31	4	T53208-68020 F/BRACE LOCK SUPPORT,	1.00	94.40		94.40
32	5	T53201-68021 FRT RADIATOR SUPPORT,	1.00	1497.60		1497.60
33	6	T53299-68010 SEAL, RADIATOR SIDE	1.00	81.30		81.30
34	7	T53289-68020 F/RADIATOR SEAL COVER,	1.00	65.20		65.20
35	8	T90975-02086 FRONT BONNET EMBLEM,	1.00	72.20		72.20
36	9	T81185-68100 UNIT,HEADLAMP LH	1.00	1280.10		1280.10
37	0	T81145-68100 UNIT,HEADLAMP RH	1.00	1280.10		1280.10
38	1	T88450-12280 A/C CONDENSER ASSY,	1.00	1820.20		1820.20
39	2	T16410-37201 RADIATOR ASSY, L/CAP	1.00	2169.60		2169.60
40	3	T16712-37040 RADIATOR SHROUD FAN 2,	1.00	94.00		94.00
41	4	T16711-37070 RADIATOR SHROUD FAN,	1.00	267.50		267.50
42	5	S08889-80102 COOLANT,SLLC&&&	1.00	80.30		80.30
43	6	T52159-68907 REAR BUMPER COVER,	1.00	596.90		596.90

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	
		Lubrication/Fluid	
		Others	Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
ndia International Insurance P L 4 Cecil Street 06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006 / ICIII1	Mr Soh Poh Hock (Su Baofu) 411A Fernvale Road #22-76 Singapore 791411 Mobile: 91893288
	Document No. 0	
	Document Date 14/07/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZGE20R	HPXNP S6	06/09/2017	SDY8382R	0	21086	67/DS/SDY8382R

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDGG20W10J007737	2ZR0A02835	60	Sam San Joi	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
44	7	T52576-68020 L/R SIDE BPR RETAINER,	1.00	46.40		all 46.40
45	8	T52156-68030 L/RR BUMPER SUPPORT,	1.00	98.60		? 98.60
46	9	T52575-68020 R/R SIDE BPR RETAINER	1.00	46.40		rel 46.40
47	0	T52155-68030 R/RR BUMPER SUPPORT	1.00	98.60		? 98.60
48	1	S52161-0K040 CLIPS	10.00	4.10		rel 41.00
49	2	T58307-68031 REAR LOWER FLR PANEL,	1.00	542.00		bt 542.00
50	3	T52181-68010 ARM,RR BUMPER	2.00	54.40		? 108.80
51	4	T57655-68010 REAR FLOOR MEMBER 2,	1.00	111.80		? 111.80
52	5	T57666-68010 L/R LWR BACK PANEL,	1.00	59.30		? 59.30
53	6	T58035-68010 R/RR FLOOR EXTENSION,	1.00	95.00		? 95.00
54	7	T67935-68020 B0 PLATE BACK DOOR	1.00	301.10		? 301.10
55	8	T58410-68020 B1 REAR DECK BOARD ASSY,	1.00	725.60		? 725.60
56	9	T67005-68041 PANEL ASSY,BACK DOOR	1.00	1493.20		bt 1493.20
57	0	T67881-68030 WEATHERSTRIP, BACK	1.00	339.30		cut 339.30
58	1	T68105-68071 REAR BACK DOOR GLASS,	1.00	1078.10	photo.	? 1078.10
59	2	T67750-68020 B1 REAR BACK DOOR BOARD,	1.00	367.30		? 367.30
60	3	U74811-13010 C2 HANDLE, DOOR PULL	1.00	23.20		x 23.20
61	4	T69350-28151 LOCK ASSY, BACK DOOR	1.00	416.80		bt 416.80
62	5	T69430-28050 STRIKER ASSY, BACK	1.00	41.40		? 41.40
63	6	T75444-68010 PLATE,LUGGAGE COMPT(VAIVE MATI	1.00	41.50		rel 41.50

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy



Borneo Motors

inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.		Customer Details			
India International Insurance P L 4 Cecil Street 06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		S1000006 / ICIII1		Mr Soh Poh Hock (Su Baofu) 411A Fernvale Road #22-76 Singapore 791411 Mobile: 91893288			
		Document No.					
		0					
		Document Date					
		14/07/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZGE20R	HPXNP S6	06/09/2017	SDY8382R	0	21086	67/DS/SDY8382R
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In	Collected On	
JTDGG20W10J007737		2ZR0A02835	60	Sam San Joi	--/------	0.00	--/------
L	Cd	Job/Parts Description		Qty	Unit Price	Disc %	Amount
64	7	T76811-68130	GARNISH, BACK DOOR,	1.00	293.30		293.30
65	8	T76817-50010	CLIP, BACK DOOR	4.00	2.50		10.00
66	9	T75819-33010	CLIP, LUGGAGE	2.00	4.00		8.00
67	0	T81561-68062	LENS,RR COMB LH	1.00	358.00		358.00
68	1	T81551-68062	LENS & BODY, RR	1.00	358.00		358.00
69	2	T81591-68020	LENS & BODY, RR	1.00	297.00		297.00
70	3	T81581-68020	LENS & BODY, RR	1.00	297.00		297.00
71	4	T89997-30070	ELECTRICAL ANTENNA,	1.00	194.20		194.20
72	5	T75443-ELGAN	ELEGANCE EMBLEM	1.00	40.00		40.00
73	6	T21000-20	SIKA 182010 SIKA TACK GO! (BLA	2.00	108.00		216.00
74	7	T21000-22	SIKA 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00
For & on behalf of		Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd						37,970.10	
		Please acknowledge receipt of vehicle		Parts 20,976.70		GST 7.00% 2,657.91	
				Labour 16,327.40		Less 0.00	
				Sublet 666.00			
				Lubrication/Fluid 0.00			
				Others 0.00		Amount Due 40,628.01	

Customer Copy