



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept			S1000006 / ICIII1		Mr Soh Poh Hock (Su Baofu) 411A Fernvale Road #22-76 Singapore 791411 Mobile: 91893288		
			Document No. 0				
			Document Date 14/07/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZGE20R	HPXNP S6	06/09/2017	SDY8382R	0	21086	67/DS/SDY8382R
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDGG20W10J007737		2ZR0A02835	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-GY861S ACC DATE:13/07/2021 DRIVE IN:14/07/2021 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				30.00	
2	S	BP-SUBLET FRT & REAR NUMBER PLATE				136.00	
3	B	BP-LAB2 CHECK LIGHTING & WIRING SYSTEM				122.40	
4	B	BP-LAB2 REMOVE & INSTALL AIRCON CONDENSER ASSY A ND CHARGE UP GAS				360.00	
5	Z	BP-SLANT SUPPLY SEALANT (NETT)- BONNET, FRT SUPPO RT PANEL				120.00	
6	B	BP-LAB2 REPLACE FRT ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN FRT ACCIDENT AFFECTED AREAS				4500.00	
7	B	BP-RES2 RESPRAY JOB ON FRT ACCIDENT AFFECTED ARE AS				2950.00	
8	S	BP-SUBLET TO RESET ECU AND REPROGRAMME				180.00	
9	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSO R				180.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept			S1000006 / ICIII1		Mr Soh Poh Hock (Su Baofu) 411A Fernvale Road #22-76 Singapore 791411 Mobile: 91893288		
			Document No. 0				
			Document Date 14/07/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZGE20R	HPXNP S6	06/09/2017	SDY8382R	0	21086	67/DS/SDY8382R
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDGG20W10J007737		2ZR0A02835	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
10	B	BP-LAB2 REMOVE & INSTALL REAR COMPARTMENT CARPET ,GARNISH AND TRIMMING TO ASSIST REPAIR				360.00	
11	B	BP-LAB2 REPLACE & INSTALL REAR WINDSCREEN GLASS				495.00	
12	S	BP-SUBLET INSTALL REAR WINDSCREEN GLASS 3M SOLAR F ILM				350.00	
13	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW TAILGATE				360.00	
14	B	BP-LAB2 REMOVE & INSTALL REAR REVERSE CAMERA				180.00	
15	Z	BP-SLANT SUPPLY SEALANT (NETT)-TAILGATE, REAR END PANEL				120.00	
16	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED REAS				3600.00	
17	B	BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED REAS				2950.00	
18	1	T52119-68909 FRONT BUMPER COVER,	1.00	596.90		596.90	
19	2	T52116-68031 L/FRT BUMPER SUPPORT,	1.00	63.40		63.40	
20	3	T52115-68031 R/FRT BUMPER SUPPORT,	1.00	63.40		63.40	
21	4	T52611-68030 FRT BUMPER ABSORBER,	1.00	103.20		103.20	
22	5	T52021-68020 FRT BPR REINFORCEMENT,	1.00	308.20		308.20	
23	6	T53101-68010 GRILLE,RADIATOR	1.00	419.30		419.30	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy

**Borneo Motors**

Inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 17 UBI ROAD 4
 SINGAPORE 408611, Tel no.: 6631 1188

**TOYOTA****ESTIMATE**

Account Details	Account No.	Customer Details
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006 / ICIII1	Mr Soh Poh Hock (Su Baofu) 411A Fernvale Road #22-76 Singapore 791411 Mobile: 91893288
	Document No. 0	
	Document Date 14/07/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZGE20R	HPXNP S6	06/09/2017	SDY8382R	0	21086	67/DS/SDY8382R
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDGG20W10J007737	2ZR0A02835	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
24	7	S52161-0K040 CLIPS	10.00	4.10		41.00
25	8	T53301-68020 FRONT BONNET ASSY,	1.00	988.40		988.40
26	9	T53341-68020 FRT BONNET INSULATOR,	1.00	415.60		415.60
27	0	T90467-09050 CLIP(HOOD INSULATOR)	6.00	2.90		17.40
28	1	T53420-68030 L/FRT BONNET HINGE,	1.00	59.60		59.60
29	2	T53410-68030 R/FRT BONNET HINGE,	1.00	59.60		59.60
30	3	T53510-68050 FRONT BONNET LOCK,	1.00	94.40		94.40
31	4	T53208-68020 F/BRACE LOCK SUPPORT,	1.00	94.40		94.40
32	5	T53201-68021 FRT RADIATOR SUPPORT,	1.00	1497.60		1497.60
33	6	T53299-68010 SEAL, RADIATOR SIDE	1.00	81.30		81.30
34	7	T53289-68020 F/RADIATOR SEAL COVER,	1.00	65.20		65.20
35	8	T90975-02086 FRONT BONNET EMBLEM,	1.00	72.20		72.20
36	9	T81185-68100 UNIT,HEADLAMP LH	1.00	1280.10		1280.10
37	0	T81145-68100 UNIT,HEADLAMP RH	1.00	1280.10		1280.10
38	1	T88450-12280 A/C CONDENSER ASSY,	1.00	1820.20		1820.20
39	2	T16410-37201 RADIATOR ASSY, L/CAP	1.00	2169.60		2169.60
40	3	T16712-37040 RADIATOR SHROUD FAN 2,	1.00	94.00		94.00
41	4	T16711-37070 RADIATOR SHROUD FAN,	1.00	267.50		267.50
42	5	S08889-80102 COOLANT,SLLC&&&	1.00	80.30		80.30
43	6	T52159-68907 REAR BUMPER COVER,	1.00	596.90		596.90

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	
		Lubrication/Fluid	Amount Due
		Others	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.		Customer Details				
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		S1000006 / ICIII1		Mr Soh Poh Hock (Su Baofu)				
		Document No. 0		411A Fernvale Road #22-76 Singapore 791411				
		Document Date 14/07/2021		Mobile: 91893288				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	ZGE20R	HPXNP S6	06/09/2017	SDY8382R	0	21086	67/DS/SDY8382R	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDGG20W10J007737		2ZR0A02835	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
44	7	T52576-68020 L/R SIDE BPR RETAINER,			1.00	46.40		46.40
45	8	T52156-68030 L/RR BUMPER SUPPORT,			1.00	98.60		98.60
46	9	T52575-68020 R/R SIDE BPR RETAINER			1.00	46.40		46.40
47	0	T52155-68030 R/RR BUMPER SUPPORT			1.00	98.60		98.60
48	1	S52161-0K040 CLIPS			10.00	4.10		41.00
49	2	T58307-68031 REAR LOWER FLR PANEL,			1.00	542.00		542.00
50	3	T52181-68010 ARM,RR BUMPER			2.00	54.40		108.80
51	4	T57655-68010 REAR FLOOR MEMBER 2,			1.00	111.80		111.80
52	5	T57666-68010 L/R LWR BACK PANEL,			1.00	59.30		59.30
53	6	T58035-68010 R/RR FLOOR EXTENSION,			1.00	95.00		95.00
54	7	T67935-68020 B0 PLATE BACK DOOR			1.00	301.10		301.10
55	8	T58410-68020 B1 REAR DECK BOARD ASSY,			1.00	725.60		725.60
56	9	T67005-68041 PANEL ASSY, BACK DOOR			1.00	1493.20		1493.20
57	0	T67881-68030 WEATHERSTRIP, BACK			1.00	339.30		339.30
58	1	T68105-68071 REAR BACK DOOR GLASS,			1.00	1078.10		1078.10
59	2	T67750-68020 B1 REAR BACK DOOR BOARD,			1.00	367.30		367.30
60	3	U74811-13010 C2 HANDLE, DOOR PULL			1.00	23.20		23.20
61	4	T69350-28151 LOCK ASSY, BACK DOOR			1.00	416.80		416.80
62	5	T69430-28050 STRIKER ASSY, BACK			1.00	41.40		41.40
63	6	T75444-68010 PLATE,LUGGAGE COMPT(VAIVE MATI			1.00	41.50		41.50
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less		
						Amount Due		

Customer Copy

**Borneo Motors**

Inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 17 UBI ROAD 4
 SINGAPORE 408611, Tel no.: 6631 1188

**TOYOTA****ESTIMATE**

Account Details			Account No.		Customer Details			
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept			S1000006 / ICIII1		Mr Soh Poh Hock (Su Baofu) 411A Fernvale Road #22-76 Singapore 791411 Mobile: 91893288			
			Document No. 0					
			Document Date 14/07/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	ZGE20R	HPXNP S6	06/09/2017	SDY8382R	0	21086	67/DS/SDY8382R	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDGG20W10J007737		2ZR0A02835	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
64	7	T76811-68130 GARNISH, BACK DOOR,			1.00	293.30		293.30
65	8	T76817-50010 CLIP, BACK DOOR			4.00	2.50		10.00
66	9	T75819-33010 CLIP, LUGGAGE			2.00	4.00		8.00
67	0	T81561-68062 LENS,RR COMB LH			1.00	358.00		358.00
68	1	T81551-68062 LENS & BODY, RR			1.00	358.00		358.00
69	2	T81591-68020 LENS & BODY, RR			1.00	297.00		297.00
70	3	T81581-68020 LENS & BODY, RR			1.00	297.00		297.00
71	4	T89997-30070 ELECTRICAL ANTENNA,			1.00	194.20		194.20
72	5	T75443-ELGAN ELEGANCE EMBLEM			1.00	40.00		40.00
73	6	T21000-20 SIKA 182010 SIKA TACK GO! (BLA			2.00	108.00		216.00
74	7	T21000-22 SIKA 207. G+P ADHESIVE PRIMER			1.00	200.00		200.00
For & on behalf of			Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd							37,970.10	
			Please acknowledge receipt of vehicle		Parts 20,976.70		GST 7.00% 2,657.91	
					Labour 16,327.40			
					Sublet 666.00		Less 0.00	
					Lubrication/Fluid 0.00			
					Others 0.00		Amount Due 40,628.01	

Customer Copy