



Borneo Motors



TOYOTA

anchape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept			S1000006 / ICIII1		Mr Soh Poh Hock (Su Baofu) 411A Fernvale Road #22-76 Singapore 791411 Mobile: 91893288		
			Document No. 0				
			Document Date 14/07/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZGE20R	HPXNP S6	06/09/2017	SDY8382R	0	21086	67/DS/SDY8382R
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDGG20W10J007737		2ZR0A02835	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-GY861S ACC DATE:13/07/2021 DRIVE IN:14/07/2021 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:					✓ 30.00
2	S	BP-SUBLET FRT & REAR NUMBER PLATE					✓ 136.00
3	B	BP-LAB2 CHECK LIGHTING & WIRING SYSTEM					✓ 122.40
4	B	BP-LAB2 REMOVE & INSTALL AIRCON CONDENSER ASSY A ND CHARGE UP GAS					✓ 360.00
5	Z	BP-SLANT SUPPLY SEALANT (NETT)- BONNET, FRT SUPPO RT PANEL					✓ 120.00
6	B	BP-LAB2 REPLACE FRT ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN FRT ACCIDENT AFFECTED AREAS					✓ 1440 4500.00
7	B	BP-RES2 RESPRAY JOB ON FRT ACCIDENT AFFECTED ARE AS					✓ 1475 2950.00
8	S	BP-SUBLET TO RESET ECU AND REPROGRAMME					✓ 180.00
9	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSO R					✓ 180.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 9729549. 12 days. Hkays p/p Rising before paint. Less tarfiku @ lkhauto.com - wp Amount Due 23/7/21 @ 2pm
Please acknowledge receipt of vehicle					Parts Labour Sublet Lubrication/Fluid Others		
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:							

Customer Copy



Borneo Motors

anchape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9

17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006 / ICIII1	Mr Soh Poh Hock (Su Baofu) 411A Fernvale Road #22-76 Singapore 791411 Mobile: 91893288
	Document No. 0	
	Document Date 14/07/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZGE20R	HPXNP S6	06/09/2017	SDY8382R	0	21086	67/DS/SDY8382R
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDGG20W10J007737	2ZR0A02835	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	B	BP-LAB2 REMOVE & INSTALL REAR COMPARTMENT CARPET, GARNISH AND TRIMMING TO ASSIST REPAIR				✓ 360.00
11	B	BP-LAB2 REPLACE & INSTALL REAR WINDSCREEN GLASS				✓ 462 495.00
12	S	BP-SUBLET INSTALL REAR WINDSCREEN GLASS 3M SOLAR F ILM				✓ 350.00
13	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW TAILGATE				✓ 360.00
14	B	BP-LAB2 REMOVE & INSTALL REAR REVERSE CAMERA				✓ 180.00
15	Z	BP-SLANT SUPPLY SEALANT (NETT)-TAILGATE, REAR END PANEL				✓ 120.00
16	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED REAS				3- 2160 2880 3600.00
17	B	BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED REAS				3- 1770 2360 2950.00
18	1	T52119-68909 FRONT BUMPER COVER,	1.00	596.90		✓ 596.90
19	2	T52116-68031 L/FRT BUMPER SUPPORT,	1.00	63.40		✓ 63.40
20	3	T52115-68031 R/FRT BUMPER SUPPORT,	1.00	63.40		✓ 63.40
21	4	T52611-68030 FRT BUMPER ABSORBER,	1.00	103.20		✓ 103.20
22	5	T52021-68020 FRT BPR REINFORCEMENT,	1.00	308.20		✓ 308.20
23	6	T53101-68010 GRILLE,RADIATOR	1.00	419.30		✓ 419.30

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors



TOYOTA

inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006 / ICIII1	Mr Soh Poh Hock (Su Baofu)
	Document No. 0	411A Fernvale Road #22-76 Singapore 791411
	Document Date 14/07/2021	Mobile: 91893288

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZGE20R	HPXNP S6	06/09/2017	SDY8382R	0	21086	67/DS/SDY8382R
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDGG20W10J007737	2ZR0A02835	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
24	7	S52161-0K040 CLIPS	10.00	4.10		41.00
25	8	T53301-68020 FRONT BONNET ASSY,	1.00	988.40		988.40
26	9	T53341-68020 FRT BONNET INSULATOR,	1.00	415.60		415.60
27	0	T90467-09050 CLIP(HOOD INSULATOR)	6.00	2.90		17.40
28	1	T53420-68030 L/FRT BONNET HINGE,	1.00	59.60		59.60
29	2	T53410-68030 R/FRT BONNET HINGE,	1.00	59.60		59.60
30	3	T53510-68050 FRONT BONNET LOCK,	1.00	59.60		59.60
31	4	T53208-68020 F/BRACE LOCK SUPPORT, - support hood lock	1.00	94.40		94.40
32	5	T53201-68021 FRT RADIATOR SUPPORT,	1.00	94.40		94.40
33	6	T53299-68010 SEAL, RADIATOR SIDE	1.00	1497.60		1497.60
34	7	T53289-68020 F/RADIATOR SEAL COVER,	1.00	81.30		81.30
35	8	T90975-02086 FRONT BONNET EMBLEM,	1.00	65.20		65.20
36	9	T81185-68100 UNIT,HEADLAMP LH	1.00	72.20		72.20
37	0	T81145-68100 UNIT,HEADLAMP RH	1.00	1280.10		1280.10
38	1	T88450-12280 A/C CONDENSER ASSY,	1.00	1280.10		1280.10
39	2	T16410-37201 RADIATOR ASSY, L/CAP	1.00	1820.20		1820.20
40	3	T16712-37040 RADIATOR SHROUD FAN 2,	1.00	2169.60		2169.60
41	4	T16711-37070 RADIATOR SHROUD FAN,	1.00	94.00		94.00
42	5	S08889-80102 COOLANT,SLLC&&&	1.00	267.50		267.50
43	6	T52159-68907 REAR BUMPER COVER,	1.00	80.30		80.30
			1.00	596.90		596.90

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006 / ICIII1	Mr Soh Poh Hock (Su Baofu) 411A Fernvale Road #22-76 Singapore 791411 Mobile: 91893288
	Document No. 0	
	Document Date 14/07/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZGE20R	HPXNP S6	06/09/2017	SDY8382R	0	21086	67/DS/SDY8382R
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDGG20W10J007737	2ZR0A02835	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
44	7	T52576-68020 L/R SIDE BPR RETAINER,	1.00	46.40		46.40 ✓
45	8	T52156-68030 L/RR BUMPER SUPPORT,	1.00	98.60		98.60 ✓
46	9	T52575-68020 R/R SIDE BPR RETAINER	1.00	46.40		46.40 ✓
47	0	T52155-68030 R/RR BUMPER SUPPORT	1.00	98.60		98.60 ✓
48	1	S52161-0K040 CLIPS	10.00	4.10		41.00 ✓
49	2	T58307-68031 REAR LOWER FLR PANEL,	1.00	542.00		542.00 ✓
50	3	T52181-68010 ARM,RR BUMPER	1.00	54.40		54.40 ✓
51	4	T57655-68010 REAR FLOOR MEMBER 2,	1.00	111.80		111.80 ✓
52	5	T57666-68010 L/R LWR BACK PANEL,	1.00	59.30		59.30 ✓
53	6	T58035-68010 R/RR FLOOR EXTENSION,	1.00	95.00		95.00 ✓
54	7	T67935-68020 B0 PLATE BACK DOOR	1.00	301.10		301.10 ✓
55	8	T58410-68020 B1 REAR DECK BOARD ASSY,	1.00	725.60		725.60 ✓
56	9	T67005-68041 PANEL ASSY,BACK DOOR	1.00	1493.20		1493.20 ✓
57	0	T67881-68030 WEATHERSTRIP, BACK	1.00	339.30		339.30 ✓
58	1	T68105-68071 REAR BACK DOOR GLASS,	1.00	1078.10		1078.10 ✓
59	2	T67750-68020 B1 REAR BACK DOOR BOARD,	1.00	367.30		367.30 ✓
60	3	U74811-13010 C2 HANDLE, DOOR PULL	1.00	23.20		23.20 ✓
61	4	T69350-28151 LOCK ASSY, BACK DOOR	1.00	416.80		416.80 ✓
62	5	T69430-28050 STRIKER ASSY, BACK	1.00	41.40		41.40 ✓
63	6	T75444-68010 PLATE,LUGGAGE COMPT(VAIVE MATI	1.00	41.50		41.50 ✓

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.		Customer Details				
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		S1000006 / ICIII1		Mr Soh Poh Hock (Su Baofu)				
		Document No. 0		411A Fernvale Road #22-76 Singapore 791411				
		Document Date 14/07/2021		Mobile: 91893288				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	ZGE20R	HPXNP S6	06/09/2017	SDY8382R	0	21086	67/DS/SDY8382R	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDGG20W10J007737		2ZR0A02835	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
64	7	T76811-68130 GARNISH, BACK DOOR,			1.00	293.30		293.30 ✓
65	8	T76817-50010 CLIP, BACK DOOR			4.00	2.50		10.00 ✓
66	9	T75819-33010 CLIP, LUGGAGE			2.00	4.00		8.00 ✓
67	0	T81561-68062 LENS,RR COMB LH			1.00	358.00		358.00 ✓
68	1	T81551-68062 LENS & BODY, RR			1.00	358.00		358.00 ✓
69	2	T81591-68020 LENS & BODY, RR			1.00	297.00		297.00 ✓
70	3	T81581-68020 LENS & BODY, RR			1.00	297.00		297.00 ✓
71	4	T89997-30070 ELECTRICAL ANTENNA,			1.00	194.20		194.20 ✓
72	5	T75443-ELGAN ELEGANCE EMBLEM			1.00	40.00		40.00 ✓
73	6	T21000-20 SIKA 182010 SIKA TACK GO! (BLA			2.00	108.00		216.00 ✓
74	7	T21000-22 SIKA 207. G+P ADHESIVE PRIMER			1.00	200.00		200.00 ✓
SUPPLEMENTARY:								
3R0 SENSOR 1 151.60 ✓ NEC PROTECTOR BACK DOOR 1 11.00 ✓ NEC PROTECTOR BACK DOOR 1 1.90 ✓ NEC PROTECTOR BACK DOOR 1 3.80 ✓ NEC PROTECTOR BACK DOOR 1 1.90 ✓ NEC EMBLEM, SYMBOL 1 72.20 ✓ NEC EXTENSION BUMPER 1 67.50 ✓ NEC								
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts 20,976.70 Labour 16,327.40 Sublet 666.00 Lubrication/Fluid 0.00 Others 0.00		37,970.10 GST 7.00% 2,657.91 Less 0.00 Amount Due 40,628.01		

Customer Copy