



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2105853

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 18/08/2021
Reference CC4/FCI21007652/R1ea3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. YM 7696G
Insured Veh. XB 9259S
Claim No. D21002068MFVS
Policy No.
Accident Date 07/07/2021
Inspection Date 15/07/2021

Description	Total
Survey Inspection	313.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	313.00
GST (7%)	21.91
Grand Total	334.91

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21007652/R1ea3q2 Date: 18/08/2021 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XB 9259S		Veh. Inspected	YM 7696G
Policy No.			Coverage (\$)	0.00
Claim No.	D21002068MFVS		Excess (\$)	0.00
Assign From	ERIC		Assign Date	14/07/2021
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI FE83BE		c.c	2977
Engine No.	HIDDEN		Year of Reg.	2007
Chassis No.	FE83BEA10413		Colour	WHITE
Odometer	696365 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	NIL
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	7.00-16	OTANI	7 mm	
L/H Front Tyre	7.00-16	OTANI	7 mm	
R/H Rear Tyre	7.00-16 (D)	OTANI	7/7 mm	
L/H Rear Tyre	7.00-16 (D)	OTANI	7/7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/07/2021		Inspection Date	15/07/2021
Survey held at	15 FAN YONG ROAD			
Repairer	MOVA AUTOMOTIVE PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YM 7696G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	BENT	2,400.00	1,750.00
1	TAILGATE LATCH RH	BENT	160.00	160.00
1	TAILGATE LOCK RH	BENT	185.00	185.00
1	TAILGATE HINGE RH	BENT	64.00	64.00
1	REAR END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR CORNER PANEL RH	BENT	120.00	120.00
2	REAR CORNER STOPPER @\$20.00	MISSING	40.00	40.00
1	SIDE GATE RH	TO REPAIR SEE LABOUR	3,750.00	-
1	TAILLAMP ASSY RH	CRACKED	265.00	265.00
1	SET REAR CANOPY (NPA)	NOT NECESSARY	-	-
	LESS 25% DISCOUNT		-1,746.00	-646.00
			5,238.00	1,938.00
	<u>SPECIAL NETT ITEMS</u>			
1	TAILGATE STICKER -60KM/H (SN)	NECESSARY	10.00	10.00
1	TAILGATE STICKER-24 PAX (SN)	NECESSARY	10.00	10.00
1	TAILGATE STICKER -GREEN COLOUR (SN)	NECESSARY	30.00	10.00
1	REVERSE SENSOR (SN)	SERVICEABLE	200.00	-
1	REAR STEP MEMBER (SN)	BENT	380.00	200.00
1	REAR PROTECTOR BAR (SN)	BENT	650.00	300.00
1	REAR NUMBER PLATE (SN)	BENT	25.00	25.00
			1,305.00	555.00
	<u>LABOUR</u>			
	TO KNOCK & STRAIGHTEN REAR END PANEL,REMOVE REPLACE ACCIDENT DAMAGED PARTS REALIGN ALL CONNECTION .INCLUSIVE OF THE REPAIR OF REAR END PANEL AND SIDE GATE RH .		800.00	600.00
	SPRAY PAINT TAILGATE REAR END PANEL ,SIDE GATE RH ,REAR STEP PANEL ,REAR CROSS MEMBER .		950.00	800.00
	REMOVE & REPLACE REVERSE SENSOR & CHECK FUNCTION .		50.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RUST PROOF AFFECTED AREAS .		90.00	40.00
			1,890.00	1,470.00
GRAND TOTAL			8,433.00	3,963.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,150.00

Report Ref No. CC4/FCI21007652/R1ea3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YM 7696G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YM 7696G

RE-INSPECTION

