

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007654/NRA3Q2
Date: 11/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070137362
Claimant Vehicle No :	SHD1188U	Insured Vehicle No :	SMV8812B
Date of Loss:	13/07/2021	Nature of Claim:	TP
		Claim No:	0648695202SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD1188U		
Make & Model:	HYUNDAI I30 GDH, 1.6 D TCI 5DR DCT (M)	Engine No:	D4FBGZ115771
Reg. Date:	22/03/2017 (Man. Year: 2016)	Chassis No:	TMAD281UVHJ125047
Colour:	Silver	Odometer:	577832 km
Engine Capacity:	1582 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Maxxis 5 mm	Rear Left Side:	Maxxis 5 mm
Front Right Side:	Maxxis 5 mm	Rear Right Side:	Maxxis 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,364.35	563.46	800.89	58.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,630.00	1,120.00	510.00	31.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,994.35	1,683.46	1,310.89	43.78
Approved Total (Overridden) (S\$)		1,300.00		

(S\$)	2,994.35	1,300.00	1,694.35	56.58
+ GST 7.00/7.00% (S\$)	209.60	91.00	118.60	56.58
Nett Amount (S\$)	3,203.95	1,391.00	1,812.95	56.58
+ Car Rental (5.0 x S\$57.30/day) (S\$)		286.50		
(S\$)		1,677.50		
Liabe Amount (50.00%) (S\$)		838.75		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		840.75		

INSPECTION

Date of Assignment: 14/07/2021

Date Inspected: 14/07/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Premier Automotive Services Pte Ltd (HQ)
 23 Changi South Ave 2, #01-02
 Singapore 486443

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	811.11 FL	*- FL
2	1		*FRONT BUMPER EMBLEM	Necessary	27.80 FL	*27.80 FL
3	1		*FRONT BUMPER O/S SIDE BRACKET	Serviceable	32.51 FL	*- FL
4	1		*FRONT O/S FENDER	Dented	514.02 FL	*514.02 FL
5	1		*SET FRONT BUMPER CLIPS	Serviceable	48.00 FS	*- FS
6	1		*FRONT O/S FENDER STICKER	Necessary	30.00 FS	*30.00 FS
7	1		*SET FRONT O/S FENDER INNER SHIELD CLIPS	Serviceable	28.00 FS	*- FS
8	1		*SET O/S DOOR STICKERS	Necessary	100.00 FS	*100.00 FS
9	1		*SUNDRY	Not Necessary	50.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	1,641.44
					- List Item Discount on L Items 20.00/20.00% (\$\$)	277.09
					Total Parts (\$\$)	1,364.35

671.82

108.36

563.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK FRONT O/S WHEEL ALIGNMENT	New	80.00	0.00
2	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	0.00
3	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE SAME	New	650.00	540.00
4	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,FRONT O/S FENDER ,FRONT O/S DOOR	New	600.00	540.00
5	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	120.00	40.00
Gross Labour Cost (S\$)			1,630.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >