

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

14-Jul-21

## ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1188 U

|      |                               |
|------|-------------------------------|
| 1 pc | Front bumper                  |
| 1 pc | Front bumper emblem           |
| 1 pc | Front bumper o/s side bracket |
| 1 pc | Front o/s fender              |

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation Less 20%
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

|    |          |       |
|----|----------|-------|
| \$ | 811.11   | XR    |
| \$ | 27.80    | NEL   |
| \$ | 32.51    | ?XSVL |
| \$ | 514.02   | DD    |
| \$ | 1,385.44 |       |
| \$ | 277.09   |       |
| \$ | 1,108.35 |       |

### S/NETT

|       |                                     |
|-------|-------------------------------------|
| 1 set | Front bumper clips                  |
| 1 pc  | Front o/s fender sticker            |
| 1 set | Front o/s fender inner shield clips |
| 1 set | o/s door stickers                   |

|    |        |       |
|----|--------|-------|
| \$ | 48.00  | XSVL  |
| \$ | 30.00  | NEL   |
| \$ | 28.00  | ?XSVL |
| \$ | 100.00 | NEL   |

### Sundry

To check front o/s wheel alignment

|    |       |     |
|----|-------|-----|
| \$ | 50.00 | XNN |
| \$ | 80.00 | XNN |

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

|    |        |     |
|----|--------|-----|
| \$ | 180.00 | XNN |
|----|--------|-----|

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same

|    |        |     |
|----|--------|-----|
| \$ | 650.00 | 540 |
|----|--------|-----|

To putty and spray painting on front bumper, front o/s fender, front o/s door

|    |        |     |
|----|--------|-----|
| \$ | 600.00 | 540 |
|----|--------|-----|

To apply rustproofing on the repaired and replaced panels.

|    |        |    |
|----|--------|----|
| \$ | 120.00 | 40 |
|----|--------|----|

|    |          |  |
|----|----------|--|
| \$ | 2,994.35 |  |
|----|----------|--|

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

PARTS \$514.82  
LESS 20% \$433.45  
S/NETT \$130.00  
LABOUR \$1,120.00

\$1,683.45

LESS 20% \$1,346.76

L1STOTAL \$1,300.00 / 3 REPAIR DAYS

NAZ LKK  
14/7/2021 1755  
L13  
3 8 9 DAYS  
CHECK ITEM PHOTO  
AFTER REPAIR PHOTO