

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

14-Jul-21

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1188 U

1 pc	Front bumper
1 pc	Front bumper emblem
1 pc	Front bumper o/s side bracket
1 pc	Front o/s fender

\$	811.11	XR
\$	27.80	NEL
\$	32.51	?
\$	514.02	DD
\$	1,385.44	
\$	277.09	
\$	1,108.35	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation Less 20%
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

S/NETT

1 set	Front bumper clips
1 pc	Front o/s fender sticker
1 set	Front o/s fender inner shield clips
1 set	o/s door stickers

\$	48.00	XSL
\$	30.00	NEL
\$	28.00	?
\$	100.00	NEL

Sundry

\$ 50.00 XNN

To check front o/s wheel alignment

\$ 80.00 XNN

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

\$ 180.00 XNN

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same

\$ 650.00 540

To putty and spray painting on front bumper, front o/s fender, front o/s door

\$ 600.00 540

To apply rustproofing on the repaired and replaced panels.

\$ 120.00 40

\$ 2,994.35

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

NAR LKK

14/7/2021 1755

LIS

38 9 DAYS

CHECK ITEM PHOTO

AFTER REPAIR PHOTO